

Request for Class II Permissive Change

FCC ID: OU9AW8001-LS

Data: December 02, 2014

TO: Federal Communication Commission

Please be notified that we, the undersigned, Guangdong Transtek Medical Electronics Co., Ltd declare that the reasons for this Class II permissive change are as below:


1. Update Host.

Please refer to below form for detailed information:

Item	Key Components Deviation		Remark
	LS203-B	LS203-B, LS202-B5, LS202-B, LS202-B1, LS202-B1 Plus, LS202-B6, LS202-B6 Plus, LS203-B6, LS203-B6 Plus, LS102-B	
Host	Wireless control Body Fat Analyzer	Glass Body Fat Analyzer	Model difference being the appearance, model name, shell and software.

Thank you.

Sincerely,


Zhongshan Transtek Electronics Co., Ltd

Tel: +86-760-88282982-230

Fax: +86-760-85339231

Email: kevintan@transtek.cn