



Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 29.MAR.2022 09:01:19

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 29.MAR.2022 09:01:39

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 29.MAR.2022 09:01:59

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 29.MAR.2022 09:02:18

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 29.MAR.2022 09:02:37

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 29.MAR.2022 09:02:54


Band 12_3 MHz_High_QPSK_RB15#0



Band 12_3 MHz_High_16QAM_RB15#0




Band 12_5 MHz_Low_QPSK_RB25#0




Date: 30.MAR.2022 13:30:37

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 30.MAR.2022 13:31:37

Band 12_5 MHz_High_QPSK_RB25#0




Date: 30.MAR.2022 13:33:07

Band 12_5 MHz_High_16QAM_RB25#0




Date: 30.MAR.2022 13:32:41

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 30.MAR.2022 13:35:51

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 30.MAR.2022 13:35:08

Band 12_10 MHz_High_QPSK_RB50#0




Date: 30.MAR.2022 13:36:47

Band 12_10 MHz_High_16QAM_RB50#0




Date: 29.MAR.2022 09:07:00

Band 17_5 MHz_Low_QPSK_RB25#0




Date: 30.MAR.2022 13:38:57

Band 17_5 MHz_Low_16QAM_RB25#0




Date: 30.MAR.2022 13:39:39

Band 17_5 MHz_High_QPSK_RB25#0




Date: 30.MAR.2022 13:40:40

Band 17_5 MHz_High_16QAM_RB25#0




Date: 30.MAR.2022 13:41:15

Band 17_10 MHz_Low_QPSK_RB50#0




Date: 21.APR.2022 20:11:22

Band 17_10 MHz_Low_16QAM_RB50#0




Date: 30.MAR.2022 13:43:11

Band 17_10 MHz_High_QPSK_RB50#0




Date: 30.MAR.2022 13:43:56

Band 17_10 MHz_High_16QAM_RB50#0




Date: 29.MAR.2022 09:10:35

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 29.MAR.2022 11:43:29

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 29.MAR.2022 11:43:51

Band 38_5 MHz_High_QPSK_RB25#0




Date: 29.MAR.2022 11:44:14

Band 38_5 MHz_High_16QAM_RB25#0




Date: 29.MAR.2022 11:44:37

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 29.MAR.2022 11:45:07

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 29.MAR.2022 11:45:29

Band 38_10 MHz_High_QPSK_RB50#0




Date: 29.MAR.2022 11:46:01

Band 38_10 MHz_High_16QAM_RB50#0




Date: 29.MAR.2022 11:46:22

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 29.MAR.2022 11:46:54

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 29.MAR.2022 11:47:23


Band 38_15 MHz_High_QPSK_RB75#0



Band 38_15 MHz_High_16QAM_RB75#0




Band 38_20 MHz_Low_QPSK_RB100#0




Date: 29.MAR.2022 11:48:51

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 29.MAR.2022 11:49:20


Band 38_20 MHz_High_QPSK_RB100#0



Band 38_20 MHz_High_16QAM_RB100#0




Band 41_5 MHz_Low_QPSK_RB25#0




Date: 29.MAR.2022 13:18:15

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 29.MAR.2022 13:18:34

Band 41_5 MHz_High_QPSK_RB25#0




Date: 29.MAR.2022 13:19:01

Band 41_5 MHz_High_16QAM_RB25#0




Date: 29.MAR.2022 13:19:20

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 29.MAR.2022 13:19:48

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 29.MAR.2022 13:20:09

Band 41_10 MHz_High_QPSK_RB50#0



Date: 29.MAR.2022 13:20:32

Band 41_10 MHz_High_16QAM_RB50#0




Date: 29.MAR.2022 13:21:03

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 30.MAR.2022 13:26:58

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 29.MAR.2022 13:22:13

Band 41_15 MHz_High_QPSK_RB75#0




Date: 30.MAR.2022 13:28:08

Band 41_15 MHz_High_16QAM_RB75#0




Date: 29.MAR.2022 13:23:09

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 29.MAR.2022 13:23:53

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 29.MAR.2022 13:24:29


Band 41_20 MHz_High_QPSK_RB100#0



Band 41_20 MHz_High_16QAM_RB100#0




Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 29.MAR.2022 16:11:56

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 29.MAR.2022 16:12:24

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 29.MAR.2022 16:12:43

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 29.MAR.2022 16:13:04

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 29.MAR.2022 16:13:36

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 29.MAR.2022 16:14:03


Band 66_3 MHz_High_QPSK_RB15#0



Band 66_3 MHz_High_16QAM_RB15#0




Band 66_5 MHz_Low_QPSK_RB25#0




Date: 29.MAR.2022 16:15:26

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 29.MAR.2022 16:15:57

Band 66_5 MHz_High_QPSK_RB25#0




Date: 29.MAR.2022 16:16:22

Band 66_5 MHz_High_16QAM_RB25#0




Date: 29.MAR.2022 16:16:53

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 29.MAR.2022 16:17:32

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 29.MAR.2022 16:18:13

Band 66_10 MHz_High_QPSK_RB50#0




Date: 29.MAR.2022 16:18:43

Band 66_10 MHz_High_16QAM_RB50#0




Date: 29.MAR.2022 16:19:18

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 29.MAR.2022 16:19:49

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 29.MAR.2022 16:20:20

Band 66_15 MHz_High_QPSK_RB75#0




Date: 29.MAR.2022 16:20:55

Band 66_15 MHz_High_16QAM_RB75#0




Date: 29.MAR.2022 16:21:23

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 29.MAR.2022 16:21:52

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 29.MAR.2022 16:22:20

Band 66_20 MHz_High_QPSK_RB100#0



Date: 29.MAR.2022 16:22:58

Band 66_20 MHz_High_16QAM_RB100#0



Date: 29.MAR.2022 16:23:29