


	Document <b>Annex C to Hearing Aid Compatibility RF Emissions Test  Report for the BlackBerry® Smartphone model RHR191LW  (SQW100-4)</b>		Page  <b>1(4)</b>
Author Data <b>Daoud Attayi</b>	Dates of Test <b>Feb. 04, April 17-27, May 14, 2015</b>	Report No <b>RTS-6067-1505-04</b>	FCC ID <b>L6ARHR190LW</b>

## Annex C: Test set up photos


	Document <b>Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RHR191LW (SQW100-4)</b>		Page <b>2(4)</b>
	Author Data <b>Daoud Attayi</b>	Dates of Test <b>Feb. 04, April 17-27, May 14, 2015</b>	Report No <b>RTS-6067-1505-04</b>

Audio Output (0, 0)




**Figure C1. BlackBerry Smartphone**

	Document <b>Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RHR191LW (SQW100-4)</b>		Page <b>3(4)</b>
Author Data <b>Daoud Attayi</b>	Dates of Test <b>Feb. 04, April 17-27, May 14, 2015</b>	Report No <b>RTS-6067-1505-04</b>	FCC ID <b>L6ARHR190LW</b>



**Figure C2 – HAC RF emissions test setup**

	Document <b>Annex C to Hearing Aid Compatibility RF Emissions Test Report for the BlackBerry® Smartphone model RHR191LW (SQW100-4)</b>		Page <b>4(4)</b>
Author Data <b>Daoud Attayi</b>	Dates of Test <b>Feb. 04, April 17-27, May 14, 2015</b>	Report No <b>RTS-6067-1505-04</b>	FCC ID <b>L6ARHR190LW</b>



**Figure C3 – HAC RF emissions test setup**