




Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15




05:59:02 15.11.2024




06:01:58 15.11.2024




Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15



06:05:10 15.11.2024




06:08:06 15.11.2024




Worldwide Testing Services(Taiwan) Co., Ltd.


Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15



06:10:54 15.11.2024




06:19:50 15.11.2024




Worldwide Testing Services(Taiwan) Co., Ltd.


Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15



06:14:22 15.11.2024



06:17:10 15.11.2024




Worldwide Testing Services(Taiwan) Co., Ltd.


Registration number: W6M22409-23739-C-3

FCC ID: IR5ML15

UNII 7





06:48:38 15.11.2024




06:46:38 15.11.2024






Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15






Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15







Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15





06:34:22 15.11.2024




06:36:14 15.11.2024






Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15








Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15








Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15






Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15






Worldwide Testing Services(Taiwan) Co., Ltd.


Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15





07:03:34 15.11.2024




06:59:34 15.11.2024




Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15







Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15




07:15:26 15.11.2024




07:30:22 15.11.2024




Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15




07:32:14 15.11.2024




07:34:22 15.11.2024




Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15




07:41:26 15.11.2024




07:39:18 15.11.2024




Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15



07:36:54 15.11.2024



07:43:42 15.11.2024



Registration number: W6M22409-23739-C-3
FCC ID: IR5ML15

