




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_16_QAM_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3570MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3624.99MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_64_QAM_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3570MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3624.99MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_DFT-s-OFDM_256_QAM_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3570MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3624.99MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_QPSK_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16QAM_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16QAM_3570MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3570MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16QAM_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16QAM_3679.98MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_16_QAM_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3570MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3624.99MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3624.99MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3624.99MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3624.99MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3624.99MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3679.98MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3679.98MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3679.98MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3679.98MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_64_QAM_3679.98MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3570MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3570MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3570MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3570MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3570MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3570MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3624.99MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3624.99MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3624.99MHz_Outer_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3624.99MHz_Inner_Full




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3624.99MHz_Inner_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3624.99MHz_Inner_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3679.98MHz_Edge_1RB_Left




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3679.98MHz_Edge_1RB_Right




n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3679.98MHz_Outer_Full



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3679.98MHz_Inner_Full



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3679.98MHz_Inner_1RB_Left



n48_30kHz_SISO_NTNV_40MHz_CP-OFDM_256_QAM_3679.98MHz_Inner_1RB_Right

