



3390 East Harmony Road
Fort Collins
Colorado 80528
United States

To whom it may concern:

This device with FCC ID: **B94HNC09CMCL** integrates a WWAN module:

	Brand	FCC ID	Date of Grant
WWAN module	FOXCONN	MCLT77W968	06/01/2018

No hardware design changes are made on the module, and the software has not been changed to increase the RF output power of the module and provided host level antenna gain is less than the original module grant. Pursuant to KDB 996369 D02, the original modular report (Report Number details see below) are submitted to represent the compliance of Part 22/24/27/90 conducted/radiated testing items of this device. Worst radiated cases found in module level testing are performed on the host level to ensure the compliance is kept.

Modular Test Report Number			
RF180321E03	RF180321E03-1	RF180321E03-2	RF180321E03-3

Sincerely,

Liang Rong Chiao

Liang Rong Chiao
Worldwide Technical Regulations
HP Inc.

10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan

frances.liang@hp.com

T +886-2-37892469