







11BE80MIMO_Ant1_5530_484+242_OFDMA_1




11BE80MIMO_Ant1_5530_484+242_OFDMA_2




11BE80MIMO_Ant1_5530_484+242_OFDMA_2




11BE80MIMO_Ant1_5530_484+242_OFDMA_3




11BE80MIMO_Ant1_5530_484+242_OFDMA_3




11BE80MIMO_Ant1_5530_484+242_OFDMA_4




11BE80MIMO_Ant1_5530_484+242_OFDMA_4




11BE80MIMO_Ant2_5530_484+242_OFDMA_1




11BE80MIMO_Ant2_5530_484+242_OFDMA_1




11BE80MIMO_Ant2_5530_484+242_OFDMA_2




11BE80MIMO_Ant2_5530_484+242_OFDMA_2




11BE80MIMO_Ant2_5530_484+242_OFDMA_3




11BE80MIMO_Ant2_5530_484+242_OFDMA_3




11BE80MIMO_Ant2_5530_484+242_OFDMA_4



11BE80MIMO_Ant2_5530_484+242_OFDMA_4




11BE80MIMO_Ant3_5530_484+242_OFDMA_1




07:27:53 31.08.2024

11BE80MIMO_Ant3_5530_484+242_OFDMA_1




07:24:00 31.08.2024


11BE80MIMO_Ant3_5530_484+242_OFDMA_2



11BE80MIMO_Ant3_5530_484+242_OFDMA_2




11BE80MIMO_Ant3_5530_484+242_OFDMA_3




07:51:37 31.08.2024

11BE80MIMO_Ant3_5530_484+242_OFDMA_3




07:49:35 31.08.2024

11BE80MIMO_Ant3_5530_484+242_OFDMA_4




07:17:59 31.08.2024

11BE80MIMO_Ant3_5530_484+242_OFDMA_4




07:12:30 31.08.2024


11BE80MIMO_Ant1_5610_484+242_OFDMA_1



11BE80MIMO_Ant1_5610_484+242_OFDMA_1




11BE80MIMO_Ant1_5610_484+242_OFDMA_2




08:09:22 31.08.2024

11BE80MIMO_Ant1_5610_484+242_OFDMA_2




08:04:06 31.08.2024


11BE80MIMO_Ant1_5610_484+242_OFDMA_3




11BE80MIMO_Ant1_5610_484+242_OFDMA_3




11BE80MIMO_Ant1_5610_484+242_OFDMA_4




11BE80MIMO_Ant1_5610_484+242_OFDMA_4




11BE80MIMO_Ant2_5610_484+242_OFDMA_1



11BE80MIMO_Ant2_5610_484+242_OFDMA_1




11BE80MIMO_Ant2_5610_484+242_OFDMA_2




08:09:44 31.08.2024

11BE80MIMO_Ant2_5610_484+242_OFDMA_2




08:06:06 31.08.2024


11BE80MIMO_Ant2_5610_484+242_OFDMA_3




11BE80MIMO_Ant2_5610_484+242_OFDMA_3




11BE80MIMO_Ant2_5610_484+242_OFDMA_4




11BE80MIMO_Ant2_5610_484+242_OFDMA_4




11BE80MIMO_Ant3_5610_484+242_OFDMA_1




11BE80MIMO_Ant3_5610_484+242_OFDMA_1




11BE80MIMO_Ant3_5610_484+242_OFDMA_2




11BE80MIMO_Ant3_5610_484+242_OFDMA_2




11BE80MIMO_Ant3_5610_484+242_OFDMA_3



11BE80MIMO_Ant3_5610_484+242_OFDMA_3




11BE80MIMO_Ant3_5610_484+242_OFDMA_4




08:35:06 31.08.2024

11BE80MIMO_Ant3_5610_484+242_OFDMA_4




08:25:33 31.08.2024


11BE80MIMO_Ant1_5775_484+242_OFDMA_1




11BE80MIMO_Ant1_5775_484+242_OFDMA_2




11BE80MIMO_Ant1_5775_484+242_OFDMA_3




11BE80MIMO_Ant1_5775_484+242_OFDMA_4




11BE80MIMO_Ant2_5775_484+242_OFDMA_1



11BE80MIMO_Ant2_5775_484+242_OFDMA_2




11BE80MIMO_Ant2_5775_484+242_OFDMA_3




01:13:43 02.09.2024

11BE80MIMO_Ant2_5775_484+242_OFDMA_4




01:24:02 02.09.2024


11BE80MIMO_Ant3_5775_484+242_OFDMA_1




11BE80MIMO_Ant3_5775_484+242_OFDMA_2




11BE80MIMO_Ant3_5775_484+242_OFDMA_3




11BE80MIMO_Ant3_5775_484+242_OFDMA_4




11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_1



11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_1




11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_2




01:51:03 02.09.2024

11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_2




01:44:11 02.09.2024

11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_3




02:02:20 02.09.2024

11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_3




01:55:34 02.09.2024


11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_4



11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_4




11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_5




02:37:35 02.09.2024

11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_5




02:30:55 02.09.2024

11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_6



02:49:08 02.09.2024

11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_6




02:42:18 02.09.2024


11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_7




11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_7




11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_8




11BE160MIMO_Ant1_5250_UNII-1_996+484+242_OFDMA_8




11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_1




11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_1




11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_2



11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_2




11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_3




02:03:05 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_3




01:58:03 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_4




02:14:49 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_4




02:09:44 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_5




02:38:18 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_5




02:33:22 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_6



02:49:52 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_6




02:44:46 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_7




03:01:01 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_7




02:55:48 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_8




03:12:22 02.09.2024

11BE160MIMO_Ant2_5250_UNII-1_996+484+242_OFDMA_8




03:07:29 02.09.2024

11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_1




02:27:34 02.09.2024

11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_1




02:24:18 02.09.2024


11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_2




11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_2




11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_3



11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_3




11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_4




02:15:37 02.09.2024

11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_4




02:12:22 02.09.2024

11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_5




02:39:06 02.09.2024

11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_5




02:35:55 02.09.2024


11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_6



11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_6




11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_7




03:01:49 02.09.2024

11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_7




02:58:22 02.09.2024


11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_8



11BE160MIMO_Ant3_5250_UNII-1_996+484+242_OFDMA_8




11BE160MIMO_Ant1_5250_UNII-2A_996+484+242_OFDMA_1




02:26:24 02.09.2024

11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 1




02:19:37 02.09.2024


11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 2



11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 2




11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 3




02:02:38 02.09.2024

11BE160MIMO_Ant1_5250_UNII-2A_996+484+242_OFDMA_3




01:55:53 02.09.2024

11BE160MIMO_Ant1_5250_UNII-2A_996+484+242_OFDMA_4




02:14:24 02.09.2024

11BE160MIMO_Ant1_5250_UNII-2A_996+484+242_OFDMA_4




02:07:36 02.09.2024


11BE160MIMO_Ant1_5250_UNII-2A_996+484+242_OFDMA_5



11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 5




11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 6




02:49:26 02.09.2024

11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 6




02:42:36 02.09.2024


11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 7




11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 7




11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 8



11BE160MIMO Ant1 5250 UNII-2A 996+484+242 OFDMA 8




11BE160MIMO Ant2 5250 UNII-2A 996+484+242 OFDMA 1




02:27:09 02.09.2024

11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_1



02:22:05 02.09.2024

11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_2




01:52:07 02.09.2024

11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_2




01:47:03 02.09.2024

11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_3



11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_3




11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_4




02:15:10 02.09.2024

11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_4




02:10:05 02.09.2024

11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_5




02:38:39 02.09.2024

11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_5




02:33:42 02.09.2024

11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_6




11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_6




11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_7




11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_7




11BE160MIMO_Ant2_5250_UNII-2A_996+484+242_OFDMA_8




11BE160MIMO Ant2 5250 UNII-2A 996+484+242 OFDMA 8




11BE160MIMO Ant3 5250 UNII-2A 996+484+242 OFDMA 1



11BE160MIMO Ant3 5250 UNII-2A 996+484+242 OFDMA 1




11BE160MIMO Ant3 5250 UNII-2A 996+484+242 OFDMA 2




01:52:55 02.09.2024

11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_2




01:49:42 02.09.2024

11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_3




02:04:12 02.09.2024

11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_3




02:00:59 02.09.2024

11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_4




11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_4




11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_5



11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_5




11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_6




02:50:59 02.09.2024

11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_6




02:47:39 02.09.2024


11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_7




11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_7




11BE160MIMO_Ant3_5250_UNII-2A_996+484+242_OFDMA_8




11BE160MIMO_Ant3 5250 UNII-2A 996+484+242 OFDMA 8




11BE160MIMO_Ant1 5570 996+484 OFDMA 1



11BE160MIMO Ant1 5570 996+484 OFDMA_1




11BE160MIMO Ant1 5570 996+484 OFDMA_2




07:01:37 02.09.2024

11BE160MIMO Ant1 5570 996+484 OFDMA 2




06:55:52 02.09.2024

11BE160MIMO Ant1 5570 996+484 OFDMA 3




07:12:01 02.09.2024

11BE160MIMO Ant1 5570 996+484 OFDMA 3




07:05:54 02.09.2024

11BE160MIMO Ant1 5570 996+484 OFDMA 4



11BE160MIMO Ant1 5570 996+484 OFDMA 4



11BE160MIMO Ant1 5570 996+484+242 OFDMA 1