



INTERTEK TESTING SERVICE

Report: 14070167HKG-005

Equipment Photographs

Model : 72601

(Internal)





INTERTEK TESTING SERVICE

Report: 14070167HKG-005

Equipment Photographs

Model : 72601

(Internal)





INTERTEK TESTING SERVICE

Report: 14070167HKG-005

Equipment Photographs

Model : 72601

(Internal)





INTERTEK TESTING SERVICE

Report: 14070167HKG-005

Equipment Photographs

Model : 72601

(Internal)





INTERTEK TESTING SERVICE

Report: 14070167HKG-005

Equipment Photographs

Model : 72601

(Internal)





INTERTEK TESTING SERVICE

Report: 14070167HKG-005

Equipment Photographs

Model : 72601

(Internal)



FCC ID: PQN7260113M56
IC: 4438B-72601