


Label Location



Part No :
Model : DA3510TAN
HW ver : V, Ω, A
Frequency range: MHz
kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :
Model : DA3500TGG
HW ver : V, Ω, A
Frequency range: MHz
kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3500TGN

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3500TGL

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3500TEG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3500TEP

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3500TAN

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3500TAU

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3520TGG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3510TEG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.

Operation Is Subject to the following two conditions :

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3510TEP

HW ver :

V, Ω, A

Frequency range:

MHz
kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3500TBB

HW ver :

V, Ω, A

Frequency range:

MHz
kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3510TAN

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3500TFN

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :
Model : DA3510TGG
HW ver : V, Ω, A
Frequency range: MHz
kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :
Model : DA3500TMG
HW ver : V, Ω, A
Frequency range: MHz
kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation Is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd

Part No :

Model : DA3530TGG

HW ver :

V, Ω, A

Frequency range:

MHz

kHz



FCC ID: TQ8-DA3510TAN

프린팅 영역(33X10)

: 승인번호 ONLY

This device complies with part 15 of the FCC Rules.
Operation is Subject to the following two conditions :
(1) this device may not cause harmful interference, and
(2) this device must accept any interference received,
including interference that may cause undesired operation

HYUNDAI MOBIS Co., Ltd