


Test Graphs



11A Ant1_5745



11A Ant1_5785



11A Ant1_5825



11N20SISO Ant1 5180



11N20SISO Ant1 5200



11N20SISO Ant1 5240



11N20SISO Ant1 5745



11N20SISO Ant1 5785



11N20SISO Ant1 5825



11N40SISO Ant1 5190



11N40SISO Ant1 5230



11N40SISO Ant1 5755



11N40SISO Ant1 5795



11AC20SISO Ant1 5180



11AC20SISO Ant1 5200



11AC20SISO Ant1 5240



11AC20SISO Ant1 5745



11AC20SISO Ant1 5785



11AC20SISO Ant1 5825



11AC40SISO Ant1 5190



11AC40SISO Ant1 5230



11AC40SISO Ant1 5755




11AC40SISO Ant1 5795



11AC80SISO Ant1 5210






Appendix D: Duty Cycle Test Result


TestMode	Antenna	Channel	Transmission Duration [ms]	Transmission Period [ms]	Duty Cycle [%]
11A	Ant1	5180	1.38	1.43	96.50
		5200	1.38	1.43	96.50
		5240	1.39	1.43	97.20
		5745	1.38	1.43	96.50
		5785	1.38	1.42	97.18
		5825	1.39	1.43	97.20
11N20SISO	Ant1	5180	1.29	1.34	96.27
		5200	1.29	1.34	96.27
		5240	1.29	1.33	96.99
		5745	1.30	1.34	97.01
		5785	1.30	1.34	97.01
		5825	1.29	1.33	96.99
11N40SISO	Ant1	5190	0.64	0.69	92.75
		5230	0.65	0.69	94.20
		5755	0.64	0.68	94.12
		5795	0.64	0.68	94.12
11AC20SISO	Ant1	5180	1.30	1.35	96.30
		5200	1.30	1.34	97.01
		5240	1.30	1.35	96.30
		5745	1.30	1.35	96.30
		5785	1.30	1.34	97.01
		5825	1.30	1.34	97.01
11AC40SISO	Ant1	5190	0.65	0.69	94.20
		5230	0.65	0.69	94.20
		5755	0.65	0.69	94.20
		5795	0.65	0.69	94.20
11AC80SISO	Ant1	5210	0.33	0.37	89.19
		5775	0.32	0.37	86.49

Test Graphs


11A_Ant1_5180




11A_Ant1_5200



11A_Ant1_5240




11A Ant1_5745




Date: 23.AUG.2021 19:37:06

11A Ant1_5785




Date: 23.AUG.2021 19:38:20

11A Ant1_5825




Date: 23.AUG.2021 19:39:42

11N20SISO_Ant1_5180




Date: 23.AUG.2021 19:40:53

11N20SISO_Ant1_5200




Date: 23.AUG.2021 19:41:55

11N20SISO_Ant1_5240




Date: 23.AUG.2021 19:42:58

11N20SISO_Ant1_5745




Date: 23.AUG.2021 19:44:20

11N20SISO_Ant1_5785




Date: 23.AUG.2021 19:45:35

11N20SISO_Ant1_5825




Date: 23.AUG.2021 19:46:59

11N40SISO_Ant1_5190




Date: 23.AUG.2021 19:49:16

11N40SISO_Ant1_5230




Date: 23.AUG.2021 19:50:27

11N40SISO_Ant1_5755




Date: 23.AUG.2021 19:54:00

11N40SISO_Ant1_5795




Date: 23.AUG.2021 19:56:18

11AC20SISO_Ant1_5180




Date: 23.AUG.2021 19:59:07

11AC20SISO_Ant1_5200




Date: 23.AUG.2021 20:00:12

11AC20SISO_Ant1_5240




Date: 23.AUG.2021 20:01:29

11AC20SISO_Ant1_5745




Date: 23.AUG.2021 20:02:51

11AC20SISO_Ant1_5785




Date: 23.AUG.2021 20:04:20

11AC20SISO_Ant1_5825




Date: 23.AUG.2021 20:05:35

11AC40SISO_Ant1_5190




Date: 23.AUG.2021 20:07:47

11AC40SISO_Ant1_5230




Date: 23.AUG.2021 20:09:30

11AC40SISO_Ant1_5755




Date: 23.AUG.2021 20:18:58

11AC40SISO_Ant1_5795




Date: 23.AUG.2021 20:20:11

11AC80SISO_Ant1_5210



Date: 23.AUG.2021 20:25:10



***** END OF REPORT *****