## **Description of Permissive Change**

The difference compared with the Report No.: RF150203E03 design changed is as the following:

- Add PCBA board under the original module board for difference interface required.
- Add two antenna ports.
- Change Test Model and Series Model.

| Original Original |               |                                   |
|-------------------|---------------|-----------------------------------|
| Brand             | Model Name    | Description                       |
| МТІ               | RU00-M03      | X= 0~9 , A~Z , Configuration Code |
|                   | RU00-M03-XXXX |                                   |
| Newly             |               |                                   |
| Brand             | Model Name    | Description                       |
| MTI               | RU00-M04      | X= 0~9 , A~Z , Configuration Code |
|                   | RU00-M04-XXXX |                                   |



Senior Specialist

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886-3-318 3232 ext. 1929

Fax: 886-3-3270892

Email: amanda.wu@tw.bureauveritas.com

Data: 2017-09-11