

Internal Photographs

For

XX6STP9080

Contents

XX6STP9080 BT FITTED.....	3
XX6STP9080 BT REMOVED.....	4
XX6STP9080 WITHOUT HEATSINK.....	5
XX6STP9080 WITHOUT CANS.....	6
XX6STP9080 LCD SIDE.....	7
XX6STP9080 LCD SIDE LESS FRAME.....	8
XX6STP9080 LCD SIDE LESS CANS.....	9
XX6STP9080 BT TOP LESS CANS.....	10
XX6STP9080 BT BOTTOM.....	11

Sepura plc


Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9080 Bluetooth fitted



Sepura plc

Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9080 Bluetooth Removed



Sepura plc

Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9080 Without Heatsink



Sepura plc


Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9080 Without Cans



Sepura plc

Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9080 LCD Side



Sepura plc


Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9080 LCD side less frame



Sepura plc


Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9080 LCD side without cans



Sepura plc


Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9080 BT TOP LESS CANS



Sepura plc

Radio House, St Andrew's Road,
Cambridge CB4 1GR, England.

Tel: + 44 (0) 1223 876000

Fax: + 44 (0) 1223 879000

sepura.com

XX6STP9080 BT bottom

