

**November 27, 2002**

**Federal Communications Commission  
Equipment Authorization Division,  
Applications Processing Branch  
7435 Oakland Mills Road  
Columbia, MD 21046**

**RE) FCC ID: BRWXR2i**

**To whom it may concern;**

**Please refer to the additional information listed below while reviewing the BRWXR2i System.**

- 1) Section 95.645 (b) states that plug-in crystals must not be accessible to the user. Indicate whether or not crystals are accessible to the user.**

Although the transmitter crystal is visible from the back of the transmitter, each crystal is glued in place prior to shipment making it a permanent installation. Consumer removal of the crystal will normally result in damage to the crystal. Therefore, frequency changes are done at the service center only.

- 2) The Manual must contain warnings per section 95.653**

- A) Please refer to the manual attachment for this information
- B) All content for operation is contained in the instruction manual.
  - 1) All instructions are contained in the instruction manual.
  - 2) There are no adjustments accessible to the user that would be in violation with the FCC rules.
  - 3) This section is not applicable to our use.

**If there is any further information required, please contact me directly at:**

**Horizon Hobby Distributors  
ATTN: Len Sabato  
Fax: 217-355-0058  
Phone: 217-403-3588  
lsabato@horizonhobby.com**