


1. Appendix: Part 15B(JBP) SETUP PHOTOS(Radiated Test)


1) RADIATED RF MEASUREMENT SETUP (30 to 1000 MHz)







2) RADIATED RF MEASUREMENT SETUP (1 to 18 GHz)







1) RADIATED RF MEASUREMENT SETUP (ABOVE 18 GHz)







2) RADIATED RF MEASUREMENT SET-UP (Axis)





3) AC LINE CONDUCTED MEASUREMENT SETUP





END OF TEST PHOTO