






LTE Band 38 64QAM 15MHz CH-Low, 100%RB




LTE Band 38 64QAM 15MHz CH-High, 100%RB




LTE Band 38 64QAM 20MHz CH-Low, 1 RB




LTE Band 38 64QAM 20MHz CH-High, 1 RB



LTE Band 38 64QAM 20MHz CH-Low, 100%RB




LTE Band 38 64QAM 20MHz CH-High, 100%RB






LTE Band 40 subset1 QPSK 5MHz CH-Low, 1 RB




14:05:50 29.11.2021

LTE Band 41 subset1 QPSK 5MHz CH-High, 1 RB




14:12:20 29.11.2021

LTE Band 40 subset1 QPSK 5MHz CH-Low, 100%RB




14:07:24 29.11.2021

LTE Band 41 subset1 QPSK 5MHz CH-High, 100%RB




14:13:32 29.11.2021

LTE Band 40 subset1 QPSK 10MHz CH-Low, 1 RB



15:05:35 29.11.2021


LTE Band 41 subset1 QPSK 10MHz CH-High, 1 RB



15:11:44 29.11.2021




LTE Band 40 subset1 QPSK 10MHz CH-Low, 100%RB




15:08:23 29.11.2021

LTE Band 41 subset1 QPSK 10MHz CH-High, 100%RB




15:13:19 29.11.2021

LTE Band 41 16QAM 5MHz CH-Low, 1 RB




14:06:27 29.11.2021

LTE Band 40 subset1 16QAM 5MHz CH-High, 1 RB




14:12:44 29.11.2021

LTE Band 40 subset1 16QAM 5MHz CH-Low, 100%RB



14:07:03 29.11.2021

LTE Band 40 subset1 16QAM 5MHz CH-High, 100%RB




14:13:09 29.11.2021



LTE Band 40 subset1 16QAM 10MHz CH-Low, 1 RB


RB



15:07:14 29.11.2021

LTE Band 40 subset1 16QAM 10MHz CH-High, 1 RB


1 RB



15:12:02 29.11.2021

LTE Band 40 subset1 16QAM 10MHz CH-Low, 100%RB


100%RB



15:07:55 29.11.2021

LTE Band 40 subset1 16QAM 10MHz CH-High, 100%RB


100%RB



15:12:49 29.11.2021

LTE Band 40 subset1 64QAM 5MHz CH-Low, 1 RB


RB



14:08:07 29.11.2021

LTE Band 40 subset1 64QAM 5MHz CH-High, 1 RB

RB



14:10:50 29.11.2021