

Report No.: 0409965
Model No.: 14105

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirements MKR 32.062 msec

REF -20.0 dBm

AT 10 dB


.02 dB

PEAK

LOG

10

dB/



WA SB

SC LS

CORR

Tested By: *[Signature]*
(Kwok Wing)

Date: 29/5/04

Checked By: *[Signature]*
(Anthony Chan)

Date: 2/6/04

Test Result: Pass / Fail / *[Initials]*

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 75.0 msec

INTERTEK TESTING SERVICES


Report No.: 0409965
Model No.: 14105

hp

Pursuant to FCC Part 15 Section 15. 235 Emissions Requirement MKR 32.062 msec

REF -20.0 dBm AT 10 dB .02 dB

PEAK
LOG
10
dB/



WA SB
SC LS
CORR

Tested By: *Ken Chan*

Date: 29/5/04

Checked By: *Anthony Chan*

Date: 31/6/04

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 45.0 msec

Report No.: 090996
Model No.: 14105

hp

Pursuant to FCC Part 15 Section 15.235 Emissions Requirements MKR 1.0120 msec

REF -20.0 dBm


AT 10 dB

-4.27 dB

PEAK

LOG

10
dB/



WA SB
SC LS
CORR

Tested By: *(Signature)*

Date: 29/5/04

Checked By: *(Signature)*
(Anthony Chan)

Date: 2/6/04

Test Result: Pass / Fail *(NA)*

CENTER 49.860 MHz

#RES BW 3.0 MHz

#VBW 3 MHz

SPAN 0 Hz

#SWP 45.0 msec

INTERTEK TESTING SERVICES

Report No.: 0409965
Model No.: 14105

hp

Pursuant to FCC Part 15 Section 15.245 Emissions Requirement MKR 450.00 μ sec

REF -20.0 dBm

AT 10 dB


-4.32 dB

PEAK

LOG

10

dB/



Tested By: Kenat Wong

Date: 29/5/04

Checked By: Anthony Chan

Date: 2/6/04

Test Result: Pass / Fail / NA

CENTER 49.860 MHz

SPAN 0 Hz

#RES BW 3.0 MHz

#VBW 3 MHz

#SWP 45.0 msec