



3390 East Harmony Road  
Fort Collins  
Colorado 80528  
United States

**Date: November 26, 2024**

FCC Laboratory  
7435 Oakland Mills Rd  
Columbia MD 21046

To whom it may concern,

Re: Change of Identification for FCC ID: B94-MT7925B22MP

We hereby request a change in identification as specified under 47 CFR §2.933 of the FCC rules. This change applies to the MediaTek module, originally granted on 01/11/2024 with FCC ID: B94-MT7925B22MP. HP Inc. intends to market the above referenced product under new FCC ID: B94-MT7925B22ME. The product bearing the new FCC ID is electrically identical to the originally certified equipment. The original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely yours,

A handwritten signature in black ink that reads 'Liang Rong Chiao'. The signature is written in a cursive style and is positioned above a horizontal line.

**Liang Rong Chiao**

Worldwide Technical Regulations  
HP International Pte. Ltd., Taiwan Branch  
10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115 Taiwan  
[frances.liang@hp.com](mailto:frances.liang@hp.com)  
T +886-2-37892469