



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 29.MAR.2022 08:24:40

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 29.MAR.2022 08:24:57


Band 2_1.4 MHz_High_QPSK_RB6#0



Band 2_1.4 MHz_High_16QAM_RB6#0




Band 2_3 MHz_Low_QPSK_RB15#0




Date: 29.MAR.2022 08:26:01

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 29.MAR.2022 08:26:18


Band 2_3 MHz_High_QPSK_RB15#0



Band 2_3 MHz_High_16QAM_RB15#0




Band 2_5 MHz_Low_QPSK_RB25#0




Date: 29.MAR.2022 08:27:22

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 29.MAR.2022 08:27:45

Band 2_5 MHz_High_QPSK_RB25#0




Date: 29.MAR.2022 08:28:11

Band 2_5 MHz_High_16QAM_RB25#0




Date: 29.MAR.2022 08:28:37


Band 2_10 MHz_Low_QPSK_RB50#0



Band 2_10 MHz_Low_16QAM_RB50#0




Band 2_10 MHz_High_QPSK_RB50#0




Date: 29.MAR.2022 08:30:05

Band 2_10 MHz_High_16QAM_RB50#0




Date: 29.MAR.2022 08:30:36


Band 2_15 MHz_Low_QPSK_RB75#0




Band 2_15 MHz_Low_16QAM_RB75#0




Band 2_15 MHz_High_QPSK_RB75#0



Band 2_15 MHz_High_16QAM_RB75#0




Band 2_20 MHz_Low_QPSK_RB100#0




Date: 29.MAR.2022 08:33:40

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 29.MAR.2022 08:34:12


Band 2_20 MHz_High_QPSK_RB100#0




Band 2_20 MHz_High_16QAM_RB100#0




Band 4_1.4 MHz_Low_QPSK_RB6#0




Band 4_1.4 MHz_Low_16QAM_RB6#0




Band 4_1.4 MHz_High_QPSK_RB6#0



Band 4_1.4 MHz_High_16QAM_RB6#0




Band 4_3 MHz_Low_QPSK_RB15#0




Date: 29.MAR.2022 08:37:05

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 29.MAR.2022 08:37:25


Band 4_3 MHz_High_QPSK_RB15#0



Band 4_3 MHz_High_16QAM_RB15#0




Band 4_5 MHz_Low_QPSK_RB25#0




Date: 29.MAR.2022 08:38:33

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 29.MAR.2022 08:38:59


Band 4_5 MHz_High_QPSK_RB25#0



Band 4_5 MHz_High_16QAM_RB25#0




Band 4_10 MHz_Low_QPSK_RB50#0




Date: 29.MAR.2022 08:40:18

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 29.MAR.2022 08:40:46

Band 4_10 MHz_High_QPSK_RB50#0




Date: 29.MAR.2022 08:41:09

Band 4_10 MHz_High_16QAM_RB50#0




Date: 29.MAR.2022 08:41:34

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 29.MAR.2022 08:42:09

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 29.MAR.2022 08:42:38

Band 4_15 MHz_High_QPSK_RB75#0




Date: 29.MAR.2022 08:43:14

Band 4_15 MHz_High_16QAM_RB75#0




Date: 29.MAR.2022 08:43:50


Band 4_20 MHz_Low_QPSK_RB100#0




Band 4_20 MHz_Low_16QAM_RB100#0




Band 4_20 MHz_High_QPSK_RB100#0



Band 4_20 MHz_High_16QAM_RB100#0




Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 29.MAR.2022 08:46:49

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 29.MAR.2022 08:47:05

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 29.MAR.2022 08:47:22

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 29.MAR.2022 08:47:39

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 29.MAR.2022 08:48:01

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 29.MAR.2022 08:48:20

Band 5_3 MHz_High_QPSK_RB15#0




Date: 29.MAR.2022 08:48:38

Band 5_3 MHz_High_16QAM_RB15#0




Date: 29.MAR.2022 08:48:54

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 29.MAR.2022 08:49:22

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 29.MAR.2022 08:49:42

Band 5_5 MHz_High_QPSK_RB25#0




Date: 29.MAR.2022 08:50:05

Band 5_5 MHz_High_16QAM_RB25#0




Date: 29.MAR.2022 08:50:25


Band 5_10 MHz_Low_QPSK_RB50#0




Band 5_10 MHz_Low_16QAM_RB50#0




Band 5_10 MHz_High_QPSK_RB50#0



Band 5_10 MHz_High_16QAM_RB50#0




Band 7_5 MHz_Low_QPSK_RB25#0




Date: 29.MAR.2022 08:52:45

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 29.MAR.2022 08:53:11

Band 7_5 MHz_High_QPSK_RB25#0




Date: 29.MAR.2022 08:53:34

Band 7_5 MHz_High_16QAM_RB25#0




Date: 29.MAR.2022 08:54:00

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 29.MAR.2022 08:54:34

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 29.MAR.2022 08:55:02

Band 7_10 MHz_High_QPSK_RB50#0




Date: 29.MAR.2022 08:55:34

Band 7_10 MHz_High_16QAM_RB50#0




Date: 29.MAR.2022 08:56:02

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 29.MAR.2022 08:56:43

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 29.MAR.2022 08:57:16

Band 7_15 MHz_High_QPSK_RB75#0




Date: 29.MAR.2022 08:57:58

Band 7_15 MHz_High_16QAM_RB75#0




Date: 29.MAR.2022 08:58:31


Band 7_20 MHz_Low_QPSK_RB100#0



Band 7_20 MHz_Low_16QAM_RB100#0




Band 7_20 MHz_High_QPSK_RB100#0



Date: 29.MAR.2022 09:00:24

Band 7_20 MHz_High_16QAM_RB100#0



Date: 29.MAR.2022 09:01:00