

From: eric@ccsemc.com.tw
Sent: Monday, January 12, 2004 10:54 PM
To: Steve Cheng
Cc: Mike Kuo; wklo@ccsemc.com.tw
Subject: ???: RE: RE: AN03T3549 Twinhead-TabletPCFCCIDFKGTABLETPC

Dear Steve,

Please find our report for the job demonstrating the compliance in radiated emission.
Please review.

Thank you!!

BR, Eric

(See attached file: (T8) B31212202-RP.pdf)

Steve Cheng	
<SCheng@CCSEMC.co	-¥óH;G "'eric@ccsemc.com.tw'"
<eric@ccsemc.com.tw>	
m>	°Æ¥»§Û°e;G Mike Kuo
<MKUO@CCSEMC.com>, wklo@ccsemc.com.tw	
Twinhead-Tablet PCFCCIDFKGTABLETPC	¥D ®;G RE: RE: AN03T3549
2004/01/13 09:26	
AM	

Hi Eric,

Although both antennas have been tested in original filling with great margin. However, due to the antenna swap, now both of them are work under different modulation and power. Please submit radiated emission measurement data to demonstrate the compliance.

Best regards,
Steve

0.11dBi for WLAN
-3.04dBi for Bluetooth
-----Original Message-----
From: eric@ccsemc.com.tw [mailto:eric@ccsemc.com.tw]
Sent: Friday, January 09, 2004 7:42 PM
To: Steve Cheng
Cc: Mike Kuo; eric@ccsemc.com.tw; wklo@ccsemc.com.tw

Subject: ???: RE: AN03T3549 Twinhead-Tablet PCFCCIDFKGTABLETPC

Dear Steve,

Please find out reply below in BLUE.

Thank you!!

BR, Eric

(See attached file: (T8) CL2ReqLetter.pdf)(See attached file:
B31212202-SAR-FCC_Revised 0109.pdf)

Steve Cheng

<eric@ccsemc.com.tw>	<SCheng@CCSEMC.co	~¥ó¤H;G "Eric (E-mail)"
	m>	°Æ¥»§Û°e;G Mike Kuo
<MKUO@CCSEMC.com>		¥D @;G RE: AN03T3549
Twinhead-Tablet PC FCCIDFKGTABLETPC		
2004/01/09 04:33		
AM		

RT for project: AN03T3549 FCCID:FKGTABLETPC Twinhead-Tablet PC

Subject:

Question #1: Since WLAN used a new antenna, Please supply radiated emission test data to demonstrate that EUT is compliance with 15.247(c)'s requirements.

(Answer #1 / by Eric: The EUT have not used a new antenna but only have both antennas with the WLAN and BT interchange. Please find them more from our revised CL2 request letter signed by the Twinhead.)

Question #2: Do both Bluetooth and WLAN share the same antenna? Or Bluetooth

still has its own antenna?

(Answer #2 / by James: No,the antennas are exchanged (class2 change).)

Question #3: Please supply internal photos to document the new antenna/s layout.

(Answer #3 / by James: We have inserted new antennas photo in the report._

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

Best Regards

Steve Cheng / TCB Technical Reviewer
Compliance Certification Services
561F Monterey Road
Morgan Hill, CA 95037
Tel:(408) 463-0885 x: 119
Fax:(408) 463-0888
scheng@ccsemc.com
<http://www.ccsemc.com>