
OUT OF BAND EMISSIONS - UMTS - AWS1700, PCS1900, CLR850



PSA-ESCI 2018.05.0






OUT OF BAND EMISSIONS - UMTS - AWS1700, PCS1900, CLR850



PSA-ESCI 2018.05.04





ERP OF FUNDAMENTAL - UMTS - CLR850, LTE BAND 2, LTE BAND 4



PSA-ESCI 2018.05.0-







Report No. MDTR0649 2/12

ERP OF FUNDAMENTAL - UMTS - CLR850, LTE BAND 2, LTE BAND 4








Report No. MDTR0649 3/12

EIRP OF FUNDAMENTAL - UMTS - AWS1700, PCS1900



PSA-ESCI 2018.05.04






Report No. MDTR0649 4/12

EIRP OF FUNDAMENTAL - UMTS - AWS1700, PCS1900



PSA-ESCI 2018.05.04






Report No. MDTR0649 5/12

OUT OF BAND EMISSIONS - LTE BAND 2, LTE BAND 4



PSA-ESCI 2018.05.0-






Report No. MDTR0649 6/12

OUT OF BAND EMISSIONS - LTE BAND 2, LTE BAND 4



PSA-ESCI 2018.05.0






Report No. MDTR0649 7/12

OUT OF BAND EMISSIONS - LTE BAND 5, LTE BAND 12



PSA-ESCI 2018.05.0






Report No. MDTR0649 8/12

OUT OF BAND EMISSIONS - LTE BAND 5, LTE BAND 12



PSA-ESCI 2018.05.0






Report No. MDTR0649 9/12

EIRP OF FUNDAMENTAL - LTE BAND 2, LTE BAND 4



PSA-ESCI 2018.05.0






Report No. MDTR0649 10/12

EIRP OF FUNDAMENTAL - LTE BAND 2, LTE BAND 4



PSA-ESCI 2018.05.0





Report No. MDTR0649 11/12