


EMC Technologies Report Number: M050322_Cert_WLL4070_11abg_NII_BT

APPENDIX K
Harmonics - WLL4070 802.11a (NII)




Harmonics – Channel 36

Date: 24.MAR.2005 14:56:33



Harmonics - Channel 42

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -1.68 dBm VBW 300 kHz
15 dBm 5.14228457 GHz SWT 9.8 s Unit dBm




Date: 24.MAR.2005 15:09:48



Harmonics - Channel 50

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl -2.13 dBm VBW 300 kHz
15 dBm 5.22044088 GHz SWT 9.8 s Unit dBm




Date: 24.MAR.2005 15:07:14



Harmonics - Channel 52

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl 2.12 dBm VBW 300 kHz
15 dBm 5.22044088 GHz SWT 9.8 s Unit dBm




Date: 24.MAR.2005 14:59:07



Harmonics - Channel 58

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl 1.36 dBm VBW 300 kHz
15 dBm 5.29859719 GHz SWT 9.8 s Unit dBm




Date: 24.MAR.2005 15:03:53



Harmonics - Channel 64

Marker 1 [T1] RBW 100 kHz RF Att 30 dB
Ref Lvl 1.64 dBm VBW 300 kHz
15 dBm 5.29859719 GHz SWT 9.8 s Unit dBm



Date: 24.MAR.2005 15:01:31

