

NETGEAR, INC.

350 East Plumeria Drive, San Jose, CA 95134, USA

Tel: 408-890-3657/Fax: 408-907-8097

DFS device channel plan and software operational declaration

Date: 2021-11-05

We, **NETGEAR, Inc.**, declare that the device, FCC ID: **PY321100531** Model Name: **MR70, MS70**, does not have Ad Hoc on “non-US frequencies” and/or on “DFS frequencies”. Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

Below is the channel / frequency plan for the device:

CH	1	2	3	4	5	6	7	8	9	10	11
Frequency (MHz)	2412	2417	2422	2427	2432	2437	2442	2447	2452	2457	2462
Scan Type	Active	Active	Active	Active	Active	Active	Active	Active	Active	Active	Active

CH	36	38	40	42	44	46	48	50				
Frequency (MHz)	5180	5190	5200	5210	5220	5230	5240	5250				
Scan Type	Active	Active	Active	Active	Active	Active	Active	Active				

CH	52	54	56	58	60	62	64					
Frequency (MHz)	5260	5270	5280	5290	5300	5310	5320					
Scan Type	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive					

CH	100	102	104	106	108	110	112	114	116	118	120	122
Frequency (MHz)	5500	5510	5520	5530	5540	5550	5560	5570	5580	5590	5600	5610
Scan Type	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive
CH	124	126	128	132	134	136	138	140	142	144		
Frequency (MHz)	5620	5630	5640	5660	5670	5680	5690	5700	5710	5720		
Scan Type	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive	Active Passive		

CH	149	151	153	155	157	159	161	165
Frequency (MHz)	5745	5755	5765	5775	5785	5795	5805	5825
Scan Type	Active	Active	Active	Active	Active	Active	Active	Active


Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by a special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before firmware upgrade. Unauthorized modification to firmware will lead to the failure of verification and thus firmware upgrade will not be allowed.

Sincerely yours,

NETGEAR, INC.

350 East Plumeria Drive, San Jose, CA 95134, USA

Tel: 408-890-3657/Fax: 408-907-8097

A handwritten signature in black ink, appearing to read "David Kay", written over a horizontal dashed line.

David Kay / Regulatory Compliance Director

Tel: 4088903657

Fax: 4089078097

E-mail: david.kay@netgear.com