




10. SETUP PHOTOS

ANTENNA PORT CONDUCTED RF MEASUREMENT SETUP





RADIATED RF MEASUREMENT SETUP (BELOW 1 GHz)






RADIATED RF MEASUREMENT SETUP (ABOVE 1 GHz)






RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION




X-AXIS BACK PHOTO



Y-AXIS FRONT PHOTO




Y-AXIS BACK PHOTO




Z-AXIS FRONT PHOTO







POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH AC ADAPTER





POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP WITH USB AND LAPTOP





END OF REPORT