

SPORTON LAB

Response For FCC Application
2005/6/24

RE: Benq
FCC ID: HFS-KMP6J1BH1

1. Retesting data and testing photo for PC peripheral mode will be re-uploaded;
Label is also updated with FCC logo and users manual includes part 2.1077.
2. RBW/VBW=120kHz/300kHz
3. DC 3.8V and 1.1 A
4. The coating is different and one of them has plastic buffer.
5. Please check the input power=100 mW on page 25.
6. The manufacturer does not provide holster and earphone.
7. It is deleted. The worst case class is class 10

.

Sincerely Yours
Daniel Lee
EMC/SAR Manager