

Appendix D. SAR Test Setup Photos



Bottom Face, Test Separation 0 mm



Bottom Face with Battery 2, Test Separation 0 mm



Bottom Face with Barcode L, Separation 0 mm



Bottom Face with Barcode P, Test Separation 0 mm



Bottom Face with USB Port, Test Separation 0 mm



Edge 2, Test Separation 0 mm




Edge 3, Test Separation 0 mm



Edge 3 with Barcode L, Test Separation 0 mm



Edge 3 with Barcode P, Test Separation 0 mm



Edge 3 with USB Port, Test Separation 0 mm



Edge 3 with Battery 2, Test Separation 0 mm