

Response to TCB EMC Questions

1. Please provide the Declaration of Conformity document for the host LIFEBOOK T3010D tablet PC.

[Provided, please refer to attachment](#)

2. Please provide higher resolution photos of Broadcom WLAN module (component and PCB side).

[Provided, please refer to revised attachment - Appendix B1](#)

3. The conducted power measurements listed in SAR report covers all 3 channels (1st, 6th and 11th) of both OFDM and DSSS, while EMC report shows 2437MHz only. Have other operating channels been checked during EMC testing? What were the readings?

[Yes, all 3 channels were tested with both OFDM and DSSS. Please refer to amended table on page 14 of the test EMC report for results for the 3 channels.](#)

4. To which modulation scheme does peak output power measurements listed on page 14 of the report belong to? (OFDM / DSSS) Is this the worst case and how much were the differences?

[Both modulations \(OFDM and DSSS\) are reported. Please refer to amended table on page 14 of the test EMC report.](#)

5. To which modulation scheme does the occupied bandwidth plots belong to? What were the differences observed between the modulations?

[Both modulations \(OFDM and DSSS\) are reported. Please refer to amended table on page 13 of the test EMC report. New Appendix H attached](#)

6. Please answer question 5 for radiated emissions test as well.

[Results/Readings clarified. Please refer to sections 4.3.1 and 4.3.2 of the test EMC report. These were the worst case results.](#)