

Page 4 / 17 **Report No.:** T180801N06

Rev. 00

Internal Photo (Model: P650IVF01.0)







Page 5 / 17

Report No.: T180801N06 Rev. 00







Page 6 / 17 **Report No.:** T180801N06

Rev. 00







Page 7 / 17 **Report No.:** T180801N06

Rev. 00




## **ANT**






Page 8 / 17 **Report No.:** T180801N06 Rev. 00



## **ANT**






Page 9 / 17 **Report No.:** T180801N06

Rev. 00







Page 10 / 17 **Report No.:** T180801N06 Rev. 00









Page 11 / 17


Report No.: T180801N06 Rev. 00








Page 12 / 17 **Report No.:** T180801N06 Rev. 00





Page 13 / 17


Report No.: T180801N06 Rev. 00





Page 14 / 17 **Report No.:** T180801N06

Rev. 00






Page 15 / 17

Report No.: T180801N06 Rev. 00









Page 16 / 17

Report No.: T180801N06 Rev. 00







Page 17 / 17

Report No.: T180801N06 Rev. 00

