

Timco Engineering, Inc.
Product Certification
13146 NW 86th Drive
Suite 400
Alachua, FL 32615
United States

Date: 7 November 2023

Attention: Application Examiner / Review Engineer

Subject: Request for a Change in Identification per Section §2.933 of the FCC Rules

Reference: FCC ID:2AJYU-8XS0002

This change in identification request applies for a new FCC ID as established in 47 CFR 2.933(b) for a currently approved device.

Per 2.933(b)

- 1.) The original identification is: FCC ID:2AJYU-8XS0001
- 2.) The original granted date is: 2 November,2023
- 3.) The equipment is electrically identical.
- 4.) The original test results are applicable and representative of this changed device
- 5.) External photographs incl. FCC ID label location info are included in this application.

The following files are electronically submitted as attachments:

- Cover Letter
- External Photos
- ID Lable and Location Info

Sincerely,

Signatory



Name: yongsheng Li
Title: Deputy General Manager
SIMCom Wireless Solutions Limited
E-mail: yongsheng.li@simcom.com