



Freq. Stability 20C 2.81V ax20 5300MHz Ant1 0 Minutes




Date: 20.09.2023 01:46:39

Freq. Stability 20C 3.3V ax20 5300MHz Ant1 0 Minutes




Date: 20.09.2023 01:47:30


Freq. Stability 20C 3.80V ax20 5300MHz Ant1 0 Minutes



Freq. Stability -20C 3.3V ax20 5300MHz Ant1 0 Minutes




Freq. Stability -10C 3.3V ax20 5300MHz Ant1 0 Minutes




Date: 20.09.2023 01:47:08

Freq. Stability 0C 3.3V ax20 5300MHz Ant1 0 Minutes




Date: 20.09.2023 01:47:16

Freq. Stability 10C 3.3V ax20 5300MHz Ant1 0 Minutes




Date: 20.09.2023 01:47:23

Freq. Stability 30C 3.3V ax20 5300MHz Ant1 0 Minutes




Date: 20.09.2023 01:47:37


Freq. Stability 40C 3.3V ax20 5300MHz Ant1 0 Minutes




Freq. Stability 50C 3.3V ax20 5300MHz Ant1 0 Minutes




Freq. Stability 20C 2.81V ax20 5320MHz Ant1 0 Minutes




Freq. Stability 20C 3.3V ax20 5320MHz Ant1 0 Minutes




Freq. Stability 20C 3.80V ax20 5320MHz Ant1 0 Minutes



Freq. Stability -20C 3.3V ax20 5320MHz Ant1 0 Minutes




Freq. Stability -10C 3.3V ax20 5320MHz Ant1 0 Minutes




Date: 20.09.2023 01:50:37

Freq. Stability 0C 3.3V ax20 5320MHz Ant1 0 Minutes




Date: 20.09.2023 01:51:04

Freq. Stability 10C 3.3V ax20 5320MHz Ant1 0 Minutes




Date: 20.09.2023 01:51:12

Freq. Stability 30C 3.3V ax20 5320MHz Ant1 0 Minutes




Date: 20.09.2023 01:51:26


Freq. Stability 40C 3.3V ax20 5320MHz Ant1 0 Minutes




Freq. Stability 50C 3.3V ax20 5320MHz Ant1 0 Minutes




Freq. Stability 20C 2.81V ax20 5500MHz Ant1 0 Minutes



Freq. Stability 20C 3.3V ax20 5500MHz Ant1 0 Minutes




Freq. Stability 20C 3.80V ax20 5500MHz Ant1 0 Minutes




Date: 20.09.2023 01:54:33

Freq. Stability -20C 3.3V ax20 5500MHz Ant1 0 Minutes




Date: 20.09.2023 01:54:41


Freq. Stability -10C 3.3V ax20 5500MHz Ant1 0 Minutes



Freq. Stability 0C 3.3V ax20 5500MHz Ant1 0 Minutes




Freq. Stability 10C 3.3V ax20 5500MHz Ant1 0 Minutes




Date: 20.09.2023 01:55:06

Freq. Stability 30C 3.3V ax20 5500MHz Ant1 0 Minutes




Date: 20.09.2023 01:55:23

Freq. Stability 40C 3.3V ax20 5500MHz Ant1 0 Minutes




Date: 20.09.2023 01:55:31

Freq. Stability 50C 3.3V ax20 5500MHz Ant1 0 Minutes




Date: 20.09.2023 01:55:40

Freq. Stability 20C 2.81V ax20 5600MHz Ant1 0 Minutes




Date: 20.09.2023 01:58:15

Freq. Stability 20C 3.3V ax20 5600MHz Ant1 0 Minutes




Date: 20.09.2023 01:59:14


Freq. Stability 20C 3.80V ax20 5600MHz Ant1 0 Minutes



Freq. Stability -20C 3.3V ax20 5600MHz Ant1 0 Minutes




Freq. Stability -10C 3.3V ax20 5600MHz Ant1 0 Minutes




Date: 20.09.2023 01:58:49

Freq. Stability 0C 3.3V ax20 5600MHz Ant1 0 Minutes




Date: 20.09.2023 01:58:58

Freq. Stability 10C 3.3V ax20 5600MHz Ant1 0 Minutes




Date: 20.07.2023 01:59:06

Freq. Stability 30C 3.3V ax20 5600MHz Ant1 0 Minutes




Date: 20.07.2023 01:59:23

Freq. Stability 40C 3.3V ax20 5600MHz Ant1 0 Minutes




Date: 20.09.2023 01:59:31

Freq. Stability 50C 3.3V ax20 5600MHz Ant1 0 Minutes




Date: 20.09.2023 01:59:40

Freq. Stability 20C 2.81V ax20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 02:02:33

Freq. Stability 20C 3.3V ax20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 02:03:32


Freq. Stability 20C 3.80V ax20 5700MHz Ant1 0 Minutes



Freq. Stability -20C 3.3V ax20 5700MHz Ant1 0 Minutes




Freq. Stability -10C 3.3V ax20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 02:03:07

Freq. Stability 0C 3.3V ax20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 02:03:15

Freq. Stability 10C 3.3V ax20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 02:03:23

Freq. Stability 30C 3.3V ax20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 02:03:40

Freq. Stability 40C 3.3V ax20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 02:03:49

Freq. Stability 50C 3.3V ax20 5700MHz Ant1 0 Minutes




Date: 20.09.2023 02:03:57

Freq. Stability 20C 2.81V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:06:42

Freq. Stability 20C 3.3V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:07:40

Freq. Stability 20C 3.80V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:06:38

Freq. Stability -20C 3.3V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:07:07

Freq. Stability -10C 3.3V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:07:15

Freq. Stability 0C 3.3V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:07:24

Freq. Stability 10C 3.3V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:07:32

Freq. Stability 30C 3.3V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:07:49

Freq. Stability 40C 3.3V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:07:37

Freq. Stability 50C 3.3V ax20 5745MHz Ant1 0 Minutes




Date: 20.09.2023 02:08:06

Freq. Stability 20C 2.81V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:11:02

Freq. Stability 20C 3.3V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:12:00

Freq. Stability 20C 3.80V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:11:18

Freq. Stability -20C 3.3V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:11:26

Freq. Stability -10C 3.3V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:11:35

Freq. Stability 0C 3.3V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:11:43

Freq. Stability 10C 3.3V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:11:32

Freq. Stability 30C 3.3V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:12:09

Freq. Stability 40C 3.3V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:12:17

Freq. Stability 50C 3.3V ax20 5785MHz Ant1 0 Minutes




Date: 20.09.2023 02:12:26

Freq. Stability 20C 2.81V ax20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 02:15:17

Freq. Stability 20C 3.3V ax20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 02:16:15

Freq. Stability 20C 3.80V ax20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 02:15:34

Freq. Stability -20C 3.3V ax20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 02:15:42

Freq. Stability -10C 3.3V ax20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 02:15:30

Freq. Stability 0C 3.3V ax20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 02:15:39

Freq. Stability 10C 3.3V ax20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 02:16:07

Freq. Stability 30C 3.3V ax20 5825MHz Ant1 0 Minutes




Date: 20.09.2023 02:16:24


Freq. Stability 40C 3.3V ax20 5825MHz Ant1 0 Minutes




Freq. Stability 50C 3.3V ax20 5825MHz Ant1 0 Minutes




Freq. Stability 20C 2.81V ax20 5180MHz Ant2 0 Minutes




Freq. Stability 20C 3.3V ax20 5180MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V ax20 5180MHz Ant2 0 Minutes



Freq. Stability -20C 3.3V ax20 5180MHz Ant2 0 Minutes




Freq. Stability -10C 3.3V ax20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 21:59:38

Freq. Stability 0C 3.3V ax20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 21:59:45

Freq. Stability 10C 3.3V ax20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 21:59:33

Freq. Stability 30C 3.3V ax20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 22:00:07

Freq. Stability 40C 3.3V ax20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 22:00:15

Freq. Stability 50C 3.3V ax20 5180MHz Ant2 0 Minutes




Date: 22.9.2023 22:00:22

Freq. Stability 20C 2.81V ax20 5200MHz Ant2 0 Minutes




Date: 22.09.2023 22:03:32

Freq. Stability 20C 3.3V ax20 5200MHz Ant2 0 Minutes




Date: 22.09.2023 22:04:23


Freq. Stability 20C 3.80V ax20 5200MHz Ant2 0 Minutes



Freq. Stability -20C 3.3V ax20 5200MHz Ant2 0 Minutes




Freq. Stability -10C 3.3V ax20 5200MHz Ant2 0 Minutes




Date: 22.09.2023 22:04:01

Freq. Stability 0C 3.3V ax20 5200MHz Ant2 0 Minutes




Date: 22.09.2023 22:04:08

Freq. Stability 10C 3.3V ax20 5200MHz Ant2 0 Minutes




Date: 22.9.2023 22:04:15

Freq. Stability 30C 3.3V ax20 5200MHz Ant2 0 Minutes




Date: 22.9.2023 22:04:30

Freq. Stability 40C 3.3V ax20 5200MHz Ant2 0 Minutes




Date: 22.9.2023 22:04:37

Freq. Stability 50C 3.3V ax20 5200MHz Ant2 0 Minutes




Date: 22.9.2023 22:04:45

Freq. Stability 20C 2.81V ax20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 22:08:04

Freq. Stability 20C 3.3V ax20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 22:08:55

Freq. Stability 20C 3.80V ax20 5240MHz Ant2 0 Minutes




Date: 22.09.2023 22:08:19

Freq. Stability -20C 3.3V ax20 5240MHz Ant2 0 Minutes




Date: 22.09.2023 22:08:26

Freq. Stability -10C 3.3V ax20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 22:08:33

Freq. Stability 0C 3.3V ax20 5240MHz Ant2 0 Minutes




Date: 22.9.2023 22:08:41

Freq. Stability 10C 3.3V ax20 5240MHz Ant2 0 Minutes




Date: 22.09.2023 22:08:48

Freq. Stability 30C 3.3V ax20 5240MHz Ant2 0 Minutes




Date: 22.09.2023 22:09:03


Freq. Stability 40C 3.3V ax20 5240MHz Ant2 0 Minutes



Freq. Stability 50C 3.3V ax20 5240MHz Ant2 0 Minutes




Freq. Stability 20C 2.81V ax20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 22:13:12

Freq. Stability 20C 3.3V ax20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 22:14:03


Freq. Stability 20C 3.80V ax20 5260MHz Ant2 0 Minutes



Freq. Stability -20C 3.3V ax20 5260MHz Ant2 0 Minutes




Freq. Stability -10C 3.3V ax20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 22:13:41

Freq. Stability 0C 3.3V ax20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 22:13:49

Freq. Stability 10C 3.3V ax20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 22:13:56

Freq. Stability 30C 3.3V ax20 5260MHz Ant2 0 Minutes




Date: 22.09.2023 22:14:10

Freq. Stability 40C 3.3V ax20 5260MHz Ant2 0 Minutes



Date: 22.9.2023 22:14:18

Freq. Stability 50C 3.3V ax20 5260MHz Ant2 0 Minutes



Date: 22.9.2023 22:14:25