



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 21.JAN.2022 18:13:34

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 21.JAN.2022 18:13:56

Band 2_1.4 MHz_Middle_QPSK_RB6#0




Date: 21.JAN.2022 18:14:19

Band 2_1.4 MHz_Middle_16QAM_RB6#0




Date: 21.JAN.2022 18:14:37

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 21.JAN.2022 18:15:00

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 21.JAN.2022 18:15:21

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 21.JAN.2022 18:22:18

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 21.JAN.2022 18:22:36

Band 2_3 MHz_Middle_QPSK_RB15#0




Date: 21.JAN.2022 18:22:59

Band 2_3 MHz_Middle_16QAM_RB15#0




Date: 21.JAN.2022 18:23:17

Band 2_3 MHz_High_QPSK_RB15#0




Date: 21.JAN.2022 18:23:37

Band 2_3 MHz_High_16QAM_RB15#0




Date: 21.JAN.2022 18:23:59

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 18:24:21

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 18:24:43

Band 2_5 MHz_Middle_QPSK_RB25#0




Date: 21.JAN.2022 18:25:07

Band 2_5 MHz_Middle_16QAM_RB25#0




Date: 21.JAN.2022 18:25:27

Band 2_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 18:25:49

Band 2_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 18:26:11

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 18:26:36

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 18:26:59

Band 2_10 MHz_Middle_QPSK_RB50#0




Date: 21.JAN.2022 18:27:24

Band 2_10 MHz_Middle_16QAM_RB50#0




Date: 21.JAN.2022 18:27:45

Band 2_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 18:28:10

Band 2_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 18:28:34

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 18:29:02

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 18:29:28

Band 2_15 MHz_Middle_QPSK_RB75#0




Date: 21.JAN.2022 18:29:59

Band 2_15 MHz_Middle_16QAM_RB75#0




Date: 21.JAN.2022 18:30:24

Band 2_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 18:30:50

Band 2_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 18:31:15

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 18:31:47

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 18:32:13

Band 2_20 MHz_Middle_QPSK_RB100#0




Date: 21.JAN.2022 18:32:39

Band 2_20 MHz_Middle_16QAM_RB100#0




Date: 21.JAN.2022 18:33:04

Band 2_20 MHz_High_QPSK_RB100#0




Date: 21.JAN.2022 18:33:34

Band 2_20 MHz_High_16QAM_RB100#0




Date: 21.JAN.2022 18:34:02

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 21.JAN.2022 18:34:24

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 21.JAN.2022 18:34:52

Band 4_1.4 MHz_Middle_QPSK_RB6#0




Date: 21.JAN.2022 18:35:12

Band 4_1.4 MHz_Middle_16QAM_RB6#0




Date: 21.JAN.2022 18:35:30

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 21.JAN.2022 18:35:53

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 21.JAN.2022 18:36:18

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 21.JAN.2022 18:36:43

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 21.JAN.2022 18:37:05

Band 4_3 MHz_Middle_QPSK_RB15#0




Date: 21.JAN.2022 18:37:27

Band 4_3 MHz_Middle_16QAM_RB15#0




Date: 21.JAN.2022 18:37:46

Band 4_3 MHz_High_QPSK_RB15#0




Date: 21.JAN.2022 18:38:05

Band 4_3 MHz_High_16QAM_RB15#0




Date: 21.JAN.2022 18:38:27

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 18:38:53

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 18:39:15

Band 4_5 MHz_Middle_QPSK_RB25#0




Date: 21.JAN.2022 18:39:37

Band 4_5 MHz_Middle_16QAM_RB25#0




Date: 21.JAN.2022 18:39:59

Band 4_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 18:40:18

Band 4_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 18:40:40

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 18:41:05

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 18:41:29

Band 4_10 MHz_Middle_QPSK_RB50#0




Date: 21.JAN.2022 18:41:50

Band 4_10 MHz_Middle_16QAM_RB50#0




Date: 21.JAN.2022 18:42:11

Band 4_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 18:42:36

Band 4_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 18:43:00

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 18:43:33

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 18:44:01

Band 4_15 MHz_Middle_QPSK_RB75#0




Date: 21.JAN.2022 18:44:30

Band 4_15 MHz_Middle_16QAM_RB75#0




Date: 21.JAN.2022 18:44:59

Band 4_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 18:45:28

Band 4_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 18:45:57

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 18:46:29

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 18:46:58

Band 4_20 MHz_Middle_QPSK_RB100#0




Date: 21.JAN.2022 18:47:24

Band 4_20 MHz_Middle_16QAM_RB100#0




Date: 21.JAN.2022 18:47:52

Band 4_20 MHz_High_QPSK_RB100#0




Date: 21.JAN.2022 18:48:22

Band 4_20 MHz_High_16QAM_RB100#0




Date: 21.JAN.2022 18:48:50

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 21.JAN.2022 18:49:19

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 21.JAN.2022 18:49:41

Band 5_1.4 MHz_Middle_QPSK_RB6#0




Date: 21.JAN.2022 18:50:07

Band 5_1.4 MHz_Middle_16QAM_RB6#0




Date: 21.JAN.2022 18:50:31

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 21.JAN.2022 18:50:51

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 21.JAN.2022 18:51:16

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 21.JAN.2022 18:51:39

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 21.JAN.2022 18:52:00

Band 5_3 MHz_Middle_QPSK_RB15#0




Date: 21.JAN.2022 18:52:26

Band 5_3 MHz_Middle_16QAM_RB15#0




Date: 21.JAN.2022 18:52:45

Band 5_3 MHz_High_QPSK_RB15#0




Date: 21.JAN.2022 18:53:10

Band 5_3 MHz_High_16QAM_RB15#0




Date: 21.JAN.2022 18:53:29

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 18:53:55

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 18:54:19

Band 5_5 MHz_Middle_QPSK_RB25#0




Date: 21.JAN.2022 18:54:45

Band 5_5 MHz_Middle_16QAM_RB25#0




Date: 21.JAN.2022 18:55:10

Band 5_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 18:55:32

Band 5_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 18:55:54

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 18:56:22

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 18:56:46

Band 5_10 MHz_Middle_QPSK_RB50#0




Date: 21.JAN.2022 18:57:11

Band 5_10 MHz_Middle_16QAM_RB50#0




Date: 21.JAN.2022 18:57:34

Band 5_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 18:57:59

Band 5_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 18:58:23

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 18:58:49

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 18:59:14

Band 7_5 MHz_Middle_QPSK_RB25#0




Date: 21.JAN.2022 18:59:36

Band 7_5 MHz_Middle_16QAM_RB25#0




Date: 21.JAN.2022 18:59:58

Band 7_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 19:00:21

Band 7_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 19:00:39

Band 7_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 19:01:08

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 19:01:32

Band 7_10 MHz_Middle_QPSK_RB50#0




Date: 21.JAN.2022 19:01:53

Band 7_10 MHz_Middle_16QAM_RB50#0




Date: 21.JAN.2022 19:02:14

Band 7_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 19:02:35

Band 7_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 19:02:59

Band 7_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 19:03:32

Band 7_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 19:04:01

Band 7_15 MHz_Middle_QPSK_RB75#0




Date: 21.JAN.2022 19:04:30

Band 7_15 MHz_Middle_16QAM_RB75#0




Date: 21.JAN.2022 19:04:58

Band 7_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 19:05:28

Band 7_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 19:05:56

Band 7_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 19:06:26

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 19:06:51

Band 7_20 MHz_Middle_QPSK_RB100#0




Date: 21.JAN.2022 19:07:20

Band 7_20 MHz_Middle_16QAM_RB100#0




Date: 21.JAN.2022 19:07:49

Band 7_20 MHz_High_QPSK_RB100#0




Date: 21.JAN.2022 19:08:18

Band 7_20 MHz_High_16QAM_RB100#0




Date: 21.JAN.2022 19:08:46

Band 38_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 20:50:22

Band 38_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 20:50:50

Band 38_5 MHz_Middle_QPSK_RB25#0




Date: 21.JAN.2022 22:08:53

Band 38_5 MHz_Middle_16QAM_RB25#0




Date: 21.JAN.2022 20:51:44

Band 38_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 20:52:13

Band 38_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 20:52:38

Band 38_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 20:53:18

Band 38_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 20:53:42

Band 38_10 MHz_Middle_QPSK_RB50#0




Date: 21.JAN.2022 20:54:09

Band 38_10 MHz_Middle_16QAM_RB50#0




Date: 21.JAN.2022 20:54:36

Band 38_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 20:55:13

Band 38_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 20:55:40

Band 38_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 20:56:24

Band 38_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 20:56:55

Band 38_15 MHz_Middle_QPSK_RB75#0




Date: 21.JAN.2022 20:57:37

Band 38_15 MHz_Middle_16QAM_RB75#0




Date: 21.JAN.2022 22:03:12

Band 38_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 20:58:51

Band 38_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 20:59:32

Band 38_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 21:00:13

Band 38_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 21:00:51

Band 38_20 MHz_Middle_QPSK_RB100#0




Date: 21.JAN.2022 22:04:34

Band 38_20 MHz_Middle_16QAM_RB100#0




Date: 21.JAN.2022 21:02:01

Band 38_20 MHz_High_QPSK_RB100#0




Date: 21.JAN.2022 21:02:37

Band 38_20 MHz_High_16QAM_RB100#0




Date: 21.JAN.2022 21:03:09

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 21.JAN.2022 22:06:52

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 21.JAN.2022 21:04:24

Band 41_5 MHz_Middle_QPSK_RB25#0




Date: 21.JAN.2022 21:04:53

Band 41_5 MHz_Middle_16QAM_RB25#0




Date: 21.JAN.2022 21:05:21

Band 41_5 MHz_High_QPSK_RB25#0




Date: 21.JAN.2022 21:05:53

Band 41_5 MHz_High_16QAM_RB25#0




Date: 21.JAN.2022 21:06:15

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 21.JAN.2022 21:06:43

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 21.JAN.2022 21:07:16

Band 41_10 MHz_Middle_QPSK_RB50#0




Date: 21.JAN.2022 21:07:47

Band 41_10 MHz_Middle_16QAM_RB50#0




Date: 21.JAN.2022 21:08:14

Band 41_10 MHz_High_QPSK_RB50#0




Date: 21.JAN.2022 21:08:45

Band 41_10 MHz_High_16QAM_RB50#0




Date: 21.JAN.2022 21:09:15

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 21.JAN.2022 21:10:06

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 21.JAN.2022 21:10:47

Band 41_15 MHz_Middle_QPSK_RB75#0




Date: 21.JAN.2022 21:11:25

Band 41_15 MHz_Middle_16QAM_RB75#0




Date: 21.JAN.2022 22:12:24

Band 41_15 MHz_High_QPSK_RB75#0




Date: 21.JAN.2022 21:12:42

Band 41_15 MHz_High_16QAM_RB75#0




Date: 21.JAN.2022 22:13:34

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 21.JAN.2022 21:13:56

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 21.JAN.2022 21:14:21

Band 41_20 MHz_Middle_QPSK_RB100#0




Date: 21.JAN.2022 21:14:50

Band 41_20 MHz_Middle_16QAM_RB100#0




Date: 21.JAN.2022 21:15:35

Band 41_20 MHz_High_QPSK_RB100#0



Date: 21.JAN.2022 21:16:04

Band 41_20 MHz_High_16QAM_RB100#0



Date: 21.JAN.2022 21:16:39