

FCC ID Label Location

TWO WAY RADIO
Model: 3208plus
FCC ID: T4K3208PLUS

518plus,518Turbo,
518G,518,3208
518R,3208R,318P



FCC RF Warning Label



Device must be restricted to occupational use to satisfy FCC RF exposure compliance. See owner's manual for specific operating requirements