


Appendix B


Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.APR.2022 13:51:32

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 24.APR.2022 13:51:58

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.APR.2022 13:52:32

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 24.APR.2022 13:52:55

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.APR.2022 13:53:29

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 24.APR.2022 13:53:48

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.APR.2022 13:54:21

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 24.APR.2022 13:54:40

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.APR.2022 13:55:15

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 24.APR.2022 13:55:44

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.APR.2022 13:56:18

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 24.APR.2022 13:56:50

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 13:57:26

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 24.APR.2022 13:57:48

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 13:58:17

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 24.APR.2022 13:58:46

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 13:59:18

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 24.APR.2022 13:59:37

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:00:18

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 24.APR.2022 14:00:44

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:01:17

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 24.APR.2022 14:01:46

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:02:20

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 24.APR.2022 14:02:45

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:03:24

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 24.APR.2022 14:03:43

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:04:25

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 24.APR.2022 14:04:44

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:05:25

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 24.APR.2022 14:05:47

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:06:30

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 24.APR.2022 14:06:49

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:07:30

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 24.APR.2022 14:07:52

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:08:34

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 24.APR.2022 14:08:56

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:09:29

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:09:54

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:10:23

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:10:42

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:11:13

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:11:39

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:12:11

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:12:30

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:13:05

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:13:34

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:14:08

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:14:34

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:15:03

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:15:29

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:16:03

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:16:26

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:16:57

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:17:19

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:17:51

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:18:20

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:18:57

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:19:19

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:19:53

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:20:24

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 24.APR.2022 14:20:57

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 24.APR.2022 14:21:19

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)



Date: 24.APR.2022 14:21:51

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)



Date: 24.APR.2022 14:22:16