




OBW&EBW N41 30KHz TM3 20MHz 518598 Outer Full




OBW&EBW N41 30KHz TM4 20MHz 518598 Outer Full




OBW&EBW N41 30KHz TM5 20MHz 518598 Outer Full




OBW&EBW N41 30KHz TM6 20MHz 518598 Outer Full




OBW&EBW N41 30KHz TM7 20MHz 518598 Outer Full




OBW&EBW N41 30KHz TM8 20MHz 518598 Outer Full







OBW&EBW N41 30KHz TM2 30MHz 518598 Outer Full




OBW&EBW N41 30KHz TM3 30MHz 518598 Outer Full




OBW&EBW N41 30KHz TM4 30MHz 518598 Outer Full




OBW&EBW N41 30KHz TM5 30MHz 518598 Outer Full




OBW&EBW N41 30KHz TM6 30MHz 518598 Outer Full




OBW&EBW N41 30KHz TM7 30MHz 518598 Outer Full







OBW&EBW N41 30KHz TM1 40MHz 518598 Outer Full




OBW&EBW N41 30KHz TM2 40MHz 518598 Outer Full




OBW&EBW N41 30KHz TM3 40MHz 518598 Outer Full




OBW&EBW N41 30KHz TM4 40MHz 518598 Outer Full




OBW&EBW N41 30KHz TM5 40MHz 518598 Outer Full




OBW&EBW N41 30KHz TM6 40MHz 518598 Outer Full




OBW&EBW N41 30KHz TM7 40MHz 518598 Outer Full




OBW&EBW N41 30KHz TM8 40MHz 518598 Outer Full







OBW&EBW N41 30KHz TM2 50MHz 518598 Outer Full




OBW&EBW N41 30KHz TM3 50MHz 518598 Outer Full




OBW&EBW N41 30KHz TM4 50MHz 518598 Outer Full




OBW&EBW N41 30KHz TM5 50MHz 518598 Outer Full




OBW&EBW N41 30KHz TM6 50MHz 518598 Outer Full




OBW&EBW N41 30KHz TM7 50MHz 518598 Outer Full







OBW&EBW N41 30KHz TM1 60MHz 518598 Outer Full




OBW&EBW N41 30KHz TM2 60MHz 518598 Outer Full




OBW&EBW N41 30KHz TM3 60MHz 518598 Outer Full




OBW&EBW N41 30KHz TM4 60MHz 518598 Outer Full




OBW&EBW N41 30KHz TM5 60MHz 518598 Outer Full




OBW&EBW N41 30KHz TM6 60MHz 518598 Outer Full




OBW&EBW N41 30KHz TM7 60MHz 518598 Outer Full




OBW&EBW N41 30KHz TM8 60MHz 518598 Outer Full






OBW&EBW N41 TM2 70MHz 518598 Outer Full




OBW&EBW N41 TM3 70MHz 518598 Outer Full







OBW&EBW N41 TM4 70MHz 518598 Outer Full




OBW&EBW N41 TM5 70MHz 518598 Outer Full





OBW&EBW N41 TM6 70MHz 518598 Outer Full




OBW&EBW N41 TM7 70MHz 518598 Outer Full









OBW&EBW N41 30KHz TM2 80MHz 518598 Outer Full




OBW&EBW N41 30KHz TM3 80MHz 518598 Outer Full




OBW&EBW N41 30KHz TM4 80MHz 518598 Outer Full




OBW&EBW N41 30KHz TM5 80MHz 518598 Outer Full




OBW&EBW N41 30KHz TM6 80MHz 518598 Outer Full




OBW&EBW N41 30KHz TM7 80MHz 518598 Outer Full







OBW&EBW N41 30KHz TM1 90MHz 518598 Outer Full




OBW&EBW N41 30KHz TM2 90MHz 518598 Outer Full




OBW&EBW N41 30KHz TM3 90MHz 518598 Outer Full




OBW&EBW N41 30KHz TM4 90MHz 518598 Outer Full




OBW&EBW N41 30KHz TM5 90MHz 518598 Outer Full




OBW&EBW N41 30KHz TM6 90MHz 518598 Outer Full




OBW&EBW N41 30KHz TM7 90MHz 518598 Outer Full




OBW&EBW N41 30KHz TM8 90MHz 518598 Outer Full







OBW&EBW N41 30KHz TM2 100MHz 518598 Outer Full




OBW&EBW N41 30KHz TM3 100MHz 518598 Outer Full




OBW&EBW N41 30KHz TM4 100MHz 518598 Outer Full




OBW&EBW N41 30KHz TM5 100MHz 518598 Outer Full



OBW&EBW N41 30KHz TM6 100MHz 518598 Outer Full




OBW&EBW N41 30KHz TM7 100MHz 518598 Outer Full





OBW&EBW N41 30KHz TM8 100MHz 518598 Outer Full




REMARK:

All antenna and all modulation had been tested, but only the worst case data displayed in this report




Band Edge for SA Test Graphs







N41 30KHz TM1 10MHz 537000 Edge 1RB Right



N41 30KHz TM1 10MHz 537000 Outer Full




N41 30KHz TM5 10MHz 500202 Edge 1RB Left



15:08:55 06.06.2021


N41 30KHz TM5 10MHz 500202 Outer Full




15:07:43 06.06.2021




N41 30KHz TM5 10MHz 537000 Edge 1RB Right




N41 30KHz TM5 10MHz 537000 Outer Full



N41 30KHz TM1 15MHz 500700 Edge 1RB Left




N41 30KHz TM1 15MHz 500700 Outer Full



Date: 17 JUN 2021 09:20:50






Date: 17.JUN.2021 09:25:33



N41 30KHz TM1 15MHz 536496 Edge 1RB Right



N41 30KHz TM1 15MHz 536496 Outer Full




N41 30KHz TM5 15MHz 500700 Edge 1RB Left




14:56:36 06.06.2021

N41 30KHz TM5 15MHz 500700 Outer Full



Date: 17.JUN.2021 09:30:51







Date: 17.JUN.2021 09:29:53



N41 30KHz TM6 15MHz 536496 Edge 1RB Right



N41 30KHz TM6 15MHz 536496 Outer Full




N41 TM1 20MHz 501204 Edge 1RB Left



14:45:46 06.06.2021

N41 TM1 20MHz 501204 Outer Full



Date: 17.JUN.2021 09:40:51

