YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD.

309, 3rd Floor, No.16, Yun Ding North Road, Huli District, Xiamen City, Fujian, China

Tel: 86-592-5702000 Fax: 86-592-5702455

Email: chenjl@yealink.com

Date: 2021-08-21

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

To whom it may concern:

The RF chip, model CC6100A, which installed in our product USB Wired Headset, Model: UH38 Dual; UH38 Mono, FCC ID: T2C-UH38, supports BDR (GFSK), EDR (π /4-DQPSK, 8DPSK), and BLE functions. For use in America and this chip will not support/enable BLE. The BLE function has been shielded by the manufacturer using the software.

Sincerely,

Signature:

Stone Lu

Vice General Manager

Stonela