


Report No.: AIT23052502FW5 FCC ID: 2A7DX-ACTIVE8



Band41-10MHz-16QAM-40620-50RB#0




Band41-10MHz-16QAM-41540-50RB#0




Band41-15MHz-QPSK-39725-75RB#0


Report No.: AIT23052502FW5 FCC ID: 2A7DX-ACTIVE8



Band41-15MHz-QPSK-40620-75RB#0




Band41-15MHz-QPSK-41515-75RB#0




Band41-15MHz-16QAM-39725-75RB#0


Report No.: AIT23052502FW5 FCC ID: 2A7DX-ACTIVE8



Band41-15MHz-16QAM-40620-75RB#0




Band41-15MHz-16QAM-41515-75RB#0




Band41-20MHz-QPSK-39750-100RB#0


Report No.: AIT23052502FW5 FCC ID: 2A7DX-ACTIVE8



Band41-20MHz-QPSK-40620-100RB#0




Band41-20MHz-QPSK-41490-100RB#0




Band41-20MHz-16QAM-39750-100RB#0

Dongguan Yaxu(AiT) Technology Limited

Report No.: AIT23052502FW5 FCC ID: 2A7DX-ACTIVE8



Band41-20MHz-16QAM-40620-100RB#0



Band41-20MHz-16QAM-41490-100RB#0

