ASPIRE 400 Tune Up Procedure

DATE: November/2020

EMS Technologies Canada, Ltd.

Ottawa, Canada

1 Aspire 400 LRU Tune-Up Procedures

No tune-up procedures are required to maintain the output power or frequency stability of the Aspire 400 Satellite Data Unit (SDU) or High Power Amplifier (HPA). Manufacturing calibration of transmitter components and reference oscillator alignment ensure compliance throughout the lifetime of the product.