



Date: Dec. 6, 2016

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Subject: Request to change in Identification

To Whom It May Concern:

This application for Change of Identification request a new FCC ID as stipulated in 47CFR 2.933(b) for presently authorized equipment.

This application by LINKSYS LLC will establish a new FCC ID under FCC ID: Q87-RE6800 for the purpose of marketing.

The original grant to LINKSYS LLC FCC ID: Q87-RE7000 will remain in effect.

Per 2.933(b)

- 1) The original identification is FCC ID: Q87-RE7000
- 2) The original grant date is April, 14, 2016.
- 3) The equipment is electrically and functionally identical. Only the model name and FCC ID number are different.
- 4) The original test results are applicable and representative of this changed device
- 5) Exterior photographs are included in this application.

Applicant: LINKSYS LLC  
Address : 121 Theory Drive, Irvine, California, United States

Signature:

A handwritten signature in black ink that reads "James Huang". The script is fluid and cursive.

Name and Title: James Huang, Manager, Regulatory Compliance  
Email: james.huang@belkin.com  
Tel: 949-265-1429

Linksys LLC  
121 Theory Drive, Irvine, CA 92617  
[www.Linksys.com](http://www.Linksys.com)  
949-270-8500