


Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 43 of 76

Annex B.ii. **Photograph 2: EUT Internal Photo**




iCtrl.M1P58-2- Uncover View



Bluetooth Antenna

iCtrl. M1P58-2- Main Board Top View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 44 of 76 www.siemic.com.cn



iCtrl. M1P58-2- Main Board Bottom View



Lift Actuator- Uncover View



Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 45 of 76 www.siemic.com.cn



Lift Actuator - Motor View



Recline Actuator-- Uncover View



Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 46 of 76 www.siemic.com.cn



Recline Actuator- Motor View




Adapter- Uncover View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 47 of 76 www.siemic.com.cn




Adapter- Main Board Top View



Adapter - Main Board Bottom View


Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 48 of 76 www.siemic.com.cn

RemoP20-Switch Box Uncover View




RemoP20-Switch Board Top View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 49 of 76 www.siemic.com.cn




RemoP20-Switch Board Bottom View




RemoP20-Control Box Uncover View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 50 of 76 www.siemic.com.cn



RemoP20-Control Board Top View



RemoP20 - Control Board Bottom View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 51 of 76 www.siemic.com.cn




HX35- UncoverView



HX35 - Main Board Top View



Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 52 of 76 www.siemic.com.cn




HX35- Main Board Bottom View




HX29- Uncover View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 53 of 76 www.siemic.com.cn



HX29- Main Board Top View




HX29- Main Board Bottom View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 54 of 76




HX24- Uncover View



HX24- Main Board Top View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 55 of 76 www.siemic.com.cn




HX24- Main Board Bottom View




HX36H Uncover View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 56 of 76 www.siemic.com.cn



HX36H Main Board Top View




HX36H Main Board Bottom View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 57 of 76 www.siemic.com.cn



Remo Button- Uncover View



Remo Button- Main Board Top View



Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 58 of 76 www.siemic.com.cn

Remo Button-Main Board Bottom View



Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 61 of 76

Annex B.iv. Photograph 4: EUT Internal Photo



iCtrl.M1P5-2- Uncover View



iCtrl.M1P8-2- Uncover View

Report No.: 13020926-FCC-E1 Issue Date: May 19, 2014 Page: 62 of 76 www.siemic.com.cn



iCtrl.M1RP5-2- Uncover View



iCtrl.M1RP8-2- Uncover View