

ASKEY COMPUTER CORP.

10F, NO.119, CHIENKANG RD., CHUNG-HO, TAIPEI TAIWAN R.O.C.

Tel: 886-2-2228-7588

Fax: 886-2-3234-9340

Description of Permissive Change

The reports are prepared for FCC class II permissive change. Please refer to below the table elaborating the differences between the original design and the revised model.

Item	Original design	Modified design
1	Original PCB layout	Modified PCB layout
2	Original component model: sky65206-11	Change component model: sky65206-13



John Chiou / Manager

Askey Computer Corp.

Tel: 886 2 2228 7588

Fax: 886 2 3234 9340

Email: jchiou@askey.com.tw

Report No.: RF940414L04B, SA940414L04B, FD940414L04B