HONEYWELL INTERNATIONAL INC. 9680 OLD BAILES RD FORT MILL SC 29707-7539 UNITED STATES TEL: 800-755-5505 FAX: 803-830-8097

DFS client device channel plan and software operational declaration

Date: 2016-07-27

We, HONEYWELL INTERNATIONAL INC. declare that the device, FCC ID: HD5-RC12ABGN Model Name: RC12ABGN, does not have "Ad Hoc on non-US frequencies" and/or "on DFS frequencies. Also, the client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.

Below is the channel / frequency plan for the device

СН	1	2	3	4	5	6	7	8	9	10	11
Frequency (MHz)	2412	2417	2422	2427	2432	2437	2442	2447	2452	2457	2462
Scan Type	Active										

СН	36	40	44	48
Frequency (MHz)	5180	5200	5220	5240
Scan Type	Active	Active	Active	Active

СН	52	56	60	64
Frequency (MHz)	5260	5280	5300	5320
Scan Type	Passive	Passive	Passive	Passive

СН	100	104	108	112	116	132	136	140
Frequency (MHz)	5500	5520	5540	5560	5580	5660	5680	5700
Scan Type	Passive							

СН	149	153	157	161	165
Frequency (MHz)	5745	5765	5785	5805	5825
Scan Type	Active	Active	Active	Active	Active

Also, on DFS channels, the WLAN driver in the device operates under the control of an AP at all times, except when in ad-hoc mode, on US non-DFS channels. The device passively scans DFS frequencies until a master device is detected. The control of this functionality is not accessible to anyone under any conditions. Furthermore, the firmware is protected by special signature and CRC checksum. Signature and CRC checksum will be calculated and verified before firmware upgrade. Unauthorized modification to firmware will lead the failure of verification thus firmware upgrade is not allowed.

Sincerely yours,

Name/Title: Michael Robinson / Product Compliance Scanning Leader Tel: 315-554-6387 Fax: 803-835-8097 E-mail: Michael.Robinson3@honeywell.com