

YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD.

309, 3rd Floor, No.16, Yun Ding North Road, Huli District, Xiamen City, Fujian, China

Tel: 86-592-5702000

Fax: 86-592-5702455

Email: chenjl@yealink.com

Date: 2021-12-09

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road


Columbia, MD 21046

To whom it may concern:

The RF chip, model QCC5127, which installed in our product Bluetooth Headset, Model: BH72, FCC ID: T2C-BH72, supports BDR (GFSK), EDR ($\pi/4$ -DQPSK, 8DPSK), BLE 1M and BLE 2M functions. For use in America and this chip will not support/enable BLE 1M and BLE 2M. The BLE 1M and BLE 2M has been shielded by the manufacturer using the software.

Sincerely,

Signature:

A handwritten signature in black ink, appearing to read "Stone Lu", is shown within a rectangular border.

Stone Lu

Vice General Manager