Norand Mobile Systems Division, EMC Test Lab DOC. NO.: 577-500-914 RIM Radio Module FCC SAR APPENDIX C, TABLET COMPUTER PHOTOS, RADIO INSTALLION FCC ID: EHACWAN-RIM902 REPORT NO: 990824-1

Page 1 of 5

MEASUREMENT/TECHNICAL REPORT



Intermec Technologies Corporation Cellular Radio Module OEM From RIM 902

REPORT NO: 990824-1

DATE: August 24, 1999

APPENDIX C

TABLET COMPUTER PHOTOGRAPHS AND RADIO INSTALLATION

Norand Mobile Systems Division, EMC Test Lab

DOC. NO.: 577-500-914 RIM Radio Module FCC SAR

APPENDIX C, TABLET COMPUTER PHOTOS, RADIO INSTALLION

FCC ID: EHACWAN-RIM902 REPORT NO: 990824-1

Page 2 of 5

Photo 1: Shows a close-up view of the RIM902 radio installed within the 6600 tablet computer.



Photo 2: Shows the RIM902 radio within the options compartment of the 6600, hard-drive lifted.



Norand Mobile Systems Division, EMC Test Lab

DOC. NO.: 577-500-914 RIM Radio Module FCC SAR

APPENDIX C, TABLET COMPUTER PHOTOS, RADIO INSTALLION

Photo 3: Shows the 6600 hard-drive installed above the RIM902 radio.




FCC ID: EHACWAN-RIM902

REPORT NO: 990824-1

Page 3 of 5

Photo 4: Shows the back of the 6600 with the options compartment closed.



Norand Mobile Systems Division, EMC Test Lab DOC. NO.: 577-500-914

RIM Radio Module FCC SAR

APPENDIX C, TABLET COMPUTER PHOTOS, RADIO INSTALLION

Photo 5: Shows the back view of the 6600 tablet computer.



FCC ID: EHACWAN-RIM902 REPORT NO: 990824-1

Page 4 of 5

Photo 6: Shows the top view of the 6600, this unit also has the optional GPS antenna.



Norand Mobile Systems Division, EMC Test Lab

DOC. NO.: 577-500-914 RIM Radio Module FCC SAR

APPENDIX C, TABLET COMPUTER PHOTOS, RADIO INSTALLION

FCC ID: EHACWAN-RIM902 REPORT NO: 990824-1

Page 5 of 5

Photo 7: Shows the 6600 within the vehicle dock and the remote antenna connected.



Please note this antenna is not approved for use with the RIM902 radio.