	Report No: <b>R3415</b> Issue No: <b>1</b>	IC ID: 8739A-STP9080 FCC ID: XX6STP9080	
	Test No: <b>T5484</b>	<b>Test Photos</b>	Page: 1 of 2



**dB Technology**  
|----- ( Cambridge Ltd. ) -----|

EMC  
Testing

EMC  
Consultancy

EMC  
Training

23, Headington Drive,  
Cambridge.  
CB1 9HE  
Tel : 01954 251974 (test site)  
or : 01223 241140 (accounts)  
Fax : 01954 251907  
web : www.dbtechnology.co.uk  
email: mail@dbtechnology.co.uk

## REPORT ON ELECTROMAGNETIC COMPATIBILITY TESTS

Performed at:  
**TWENTY PENCE TEST SITE**

Twenty Pence Road,  
Cottenham,  
Cambridge  
U.K.  
CB24 8PS

on

**Sepura PLC**

**STP9080**

dated


**5th November 2014**

### Document History

Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	5/11/14		Initial release		

Based on report template:  
v090319

*This report shall not be reproduced except in full, without the written approval of:  
dB Technology (Cambridge) Ltd.*

	Report No: <b>R3415</b> Issue No: <b>1</b>	IC ID: 8739A-STP9080 FCC ID: XX6STP9080	
	Test No: <b>T5484</b>	<b>Test Photos</b>	Page: 2 of 2



**Photograph 1 Radiated Emissions**



**Photograph 2 Radiated Emissions**

*This report shall not be reproduced except in full, without the written approval of:  
dB Technology (Cambridge) Ltd.*