

Response to E04-000096-1

1. The antenna is just packaged smaller and sits flat on a table instead of standing upright as the first two antennas did.
2. Updated schematics and assembly drawings and photos have been uploaded.
3. The receive antenna (Mag Loop) below 30MHz was located at its fixed calibrated height and was rotated between the E and H field polarities when a signal was found from the EUT.
4. A confidentiality letter has been uploaded.