



Photographs of the Device

Internal Front View – Modem Module




Photographs of the Device

Internal Front View – Modem Module Top View – Cover Removed



Photographs of the Device

Internal Front View – Modem Module Bottom View – Heat Sink Removed



APPLICANT: MOTOROLA SOLUTIONS

**EQUIPMENT TYPE: ABZ99FT3095
109AB-99FT3095**

Photographs of the Device

Internal Front View – Power Amplifier Module




APPLICANT: MOTOROLA SOLUTIONS

EQUIPMENT TYPE: ABZ99FT3095
109AB-99FT3095


Photographs of the Device

Internal Front View – Power Amplifier Module – Top View, Cover Removed



Photographs of the Device

Internal Front View – Power Amplifier Module – Bottom View, Heat Sink Removed



APPLICANT: MOTOROLA SOLUTIONS

**EQUIPMENT TYPE: ABZ99FT3095
109AB-99FT3095**


Photographs of the Device

Internal Front View – Power Supply Module



Photographs of the Device

Internal Front View – Wireline Board Top View



Photographs of the Device

APPLICANT: MOTOROLA SOLUTIONS

**EQUIPMENT TYPE: ABZ99FT3095
109AB-99FT3095**

Internal Front View – Wireline Board Bottom View




EXHIBIT C2-9