

Mike Kuo

From: Idy [Idy@certitek.com]
Sent: November 24 日 2003 年 Monday 11:54 PM
To: Mike Kuo
Subject: Re: [TCB] Corecess 3213N / Corecess Inc / VDSL Modem test-setup.pdf [01/10]



BlockDiagram.pdf



CC3213N
manual.pdf



external.pdf



internal.pdf



label.pdf



report.pdf



test-setup.pdf

Dear

Mike Kuo

Thank you for your cooperation.

I am sorry for my mistake.
Please see the attached file.

This project is very urgent.
If you possible, please send me TCB Approval sheet in today.

I'm sorry.

Best Regards.

Brucelim.

----- Original Message -----

From: "Mike Kuo" <MKUO@CCSEMC.com>

To: "'Idy'" <Idy@certitek.com>

Sent: Tuesday, November 25, 2003 12:18 PM

Subject: RE: [TCB] Corecess 3213N / Corecess Inc / VDSL Modem test-setup.pdf [01/10]

> Hi Bluce :

>

> Question #1: User manual does not contain information required under
> section 15.21 of FCC rules. Please provide revised user manual to comply
> this requirement.

>

> Question #2: Please provide internal photo of AC/DC adapter.

>

> Best Regards

>

> Mike Kuo

>

> > -----Original Message-----

> > From: Idy [mailto:Idy@certitek.com]

> > Sent: Monday, November 24, 2003 5:17 PM

> > To: Mike Kuo
> > Subject: Fw: [TCB] Corecess 3213N / Corecess Inc / VDSL Modem test-
> > setup.pdf [01/10]
> > Importance: High
> >
> > << Message: Untitled Attachment >> << File: report.pdf >>