Photographs

Front View





C) Always remove mains plug from wall socket before any service operations. Never remove covers unless qualified to do so. This unit contains dangerous voltages. CHASSIS NO.: V2017 must accept any interference received, including interference that may cause undersired operation. following two conditions: (1) This device may not cause harmful interference, and (2) This device BISPLAYS X-Ray emission Monitor complies with DHHS rules 21 CFR subchapter J applicable at date of manufacture. This device complies with part 15 of the FCC Rules. Operation is subject to the Cet appareil numerque de la classe B est conforme à la normo NMB-003 du Canada Apparaten skall anslutas till jordat uttag när den ansluts till ett nätverk. This class B digital apparatus complies with Canadian ICES-003 A) This apparatus must be earthed. B) Live parts are made accessible when backcover is removed. Apparatet ma kun tilkoples jordet stikkontakt. Laite on Illrettäva suojakosketinpisterasiaan. FCC ID: A3KM119 WARNING MADE IN CHINA CSI Fujitsu Siemens Computers 100-240V ~ 50-60Hz, 1.6-0.8A SCENICVIEW E772-1 S26361-K931-V150 Bgm.-Ulrich-Str. 100 Ser. No.: YEAX00001 G4/XX 86199 Augsburg Farb-Monitor Germany Rev.: 01