Hangzhou AcoSound Technology Co.,Ltd.

Room 401, No. 2 Building, No. 1390 Cangxing Street, Yuhang, Hangzhou, Zhejiang, China

Tel:+8618257251425 Fax: 0571-81021869

Email:quality01@acosound.com


Date: 2023-07-21

FCC certification No. Cover Letter


We, Hangzhou AcoSound Technology Co.,Ltd., hereby submit justification for placing the FCC certification No. in the associated user's manual and package.

According to the FCC regulation, the FCC certification No. should be printed on the hearing aid, but as the hearing aid are too small to print the label (FCC ID: 2AWQLW-IF-P), it will be moved to the user manual and package. The details are as below:

A. Side surface (A): The side surface does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.



B. Top cover (B): The top cover does not provide enough physical space to fit the printing of the FCC certification No. according to below reference picture.



Conclusion: Based on the above description of area A to B, we conclude that the device is unquestionably too small for enabling the FCC certification No. to be printed onto any surface. We therefore request to move the FCC certification No. to the user's manual and package.

Label and label location:



Bluetooth hearing aid

model: W-IF-P

Production enterprise: Hangzhou AcoSound Technology Co.,Ltd.

Production address: Room 401, No.2 Building, No.1390 Cangxing Street, Yuhang,

Hangzhou , Zhejiang, China

Production registration certificate number: 浙械注准 20172190744(Zhejiang

instrument registration 20172190744)

Production license number: 浙药监械生产许 20150024 号(Zhejiang Drug

Administration machinery production Xu 20150024)

FCC ID: 2AWQLW-IF-P



Best regards,

Signature:

Vi Bowen

Li Bowen

Quality Supervisor