

DIGI INTERNATIONAL

Hopkins, MN 55343, USA Tel: +1 (952) 912-3444 Fax: +1 (952) 912-4991

October 22, 2021

Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, Maryland 21046

Re: Cover Letter: Non-SDR for FCC ID: MCQ-EX50W

To whom it may concern:

The following five questions determine that the radio is **not an SDR**:

1. Can the RF parameters of the device be altered through software?

Yes, go to question 2. No, not an SDR.

MCQ-EX50W: Yes

2. Can third parties not permitted by the Commission through specific filings modify, configure, or load different software, or make configuration settings to operate the device or host hardware radio frequency parameters in any other way than expected to be granted?

Yes, must be an SDR. No, go to question 3.

MCQ-EX50W: No

3. Is the device capable of operating in any other in any other way than granted, or will be, granted?

Yes, go to question 4. No, go to question 5.

MCQ-EX50W: No

4. [Question not applicable]

5. Does the manufacturer elect SDR?

Yes, elects to be an SDR. No, not an SDR.

MCQ-EX50W: No

Sincerely,

Name: Harald Remmert

J. Rent

Title: Sr. Director of Engineering