



Freq. Stability 20C 2.81V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:34:05

Freq. Stability 20C 3.3V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:35:38

Freq. Stability 20C 3.80V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:34:32

Freq. Stability -20C 3.3V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:34:45

Freq. Stability -10C 3.3V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:34:38

Freq. Stability 0C 3.3V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:35:11

Freq. Stability 10C 3.3V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:35:24

Freq. Stability 30C 3.3V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:35:31

Freq. Stability 40C 3.3V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:36:04

Freq. Stability 50C 3.3V n40 5270MHz Ant1 0 Minutes




Date: 20.09.2023 02:36:17

Freq. Stability 20C 2.81V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:40:03

Freq. Stability 20C 3.3V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:41:35

Freq. Stability 20C 3.80V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:40:29

Freq. Stability -20C 3.3V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:40:42

Freq. Stability -10C 3.3V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:40:55

Freq. Stability 0C 3.3V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:41:08

Freq. Stability 10C 3.3V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:41:21

Freq. Stability 30C 3.3V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:41:48

Freq. Stability 40C 3.3V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:42:01

Freq. Stability 50C 3.3V n40 5310MHz Ant1 0 Minutes




Date: 20.09.2023 02:42:14

Freq. Stability 20C 2.81V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:45:26

Freq. Stability 20C 3.3V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:46:58

Freq. Stability 20C 3.80V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:43:32

Freq. Stability -20C 3.3V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:46:06

Freq. Stability -10C 3.3V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:46:19

Freq. Stability 0C 3.3V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:46:32

Freq. Stability 10C 3.3V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:46:45

Freq. Stability 30C 3.3V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:47:12

Freq. Stability 40C 3.3V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:47:25

Freq. Stability 50C 3.3V n40 5510MHz Ant1 0 Minutes




Date: 20.09.2023 02:47:38

Freq. Stability 20C 2.81V n40 5590MHz Ant1 0 Minutes




Date: 20.09.2023 02:50:33

Freq. Stability 20C 3.3V n40 5590MHz Ant1 0 Minutes




Date: 20.09.2023 02:52:05

Freq. Stability 20C 3.80V n40 5590MHz Ant1 0 Minutes



Date: 20.09.2023 02:50:39

Freq. Stability -20C 3.3V n40 5590MHz Ant1 0 Minutes



Date: 20.09.2023 02:51:12

Freq. Stability -10C 3.3V n40 5590MHz Ant1 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 4.14 dB RBW 10 kHz
 Att 30 dB SWF 80 ms VBW 30 kHz Mode Sweep
 SGL Count 25/25

1Pk Max

M1[1] -31.11 dBm
 5.5900000 GHz
 M2[1] -20.00 dBm
 5.5717600 GHz

CF 5.59 GHz 1001 pts Span 80.0 MHz

Marker	Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1			1	5.59 GHz	-31.11 dBm		
M2			1	5.57176 GHz	-20.00 dBm		
M3			1	5.50824 GHz	-19.13 dBm		

Date: 20.07.2023 02:51:26

Freq. Stability OC 3.3V n40 5590MHz Ant1 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 4.14 dB RBW 10 kHz
 Att 30 dB SWT 80 ms VBW 30 kHz Mode Sweep
 SGL Count 25/25

1Pk Max


M1[1] -27.38 dBm
 5.5900000 GHz
 M2[1] -20.35 dBm
 5.5717600 GHz

CF 5.59 GHz 1001 pts Span 80.0 MHz

Marker	Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1			1	5.59 GHz	-27.38 dBm		
M2			1	5.57176 GHz	-20.35 dBm		
M3			1	5.50824 GHz	-18.75 dBm		


Date: 20.07.2023 02:51:39

Freq. Stability 10C 3.3V n40 5590MHz Ant1 0 Minutes




Date: 20.09.2023 02:51:32

Freq. Stability 30C 3.3V n40 5590MHz Ant1 0 Minutes




Date: 20.09.2023 02:52:18

Freq. Stability 40C 3.3V n40 5590MHz Ant1 0 Minutes




Date: 20.09.2023 02:52:31

Freq. Stability 50C 3.3V n40 5590MHz Ant1 0 Minutes




Date: 20.09.2023 02:52:44

Freq. Stability 20C 2.81V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:55:32

Freq. Stability 20C 3.3V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:57:24

Freq. Stability 20C 3.80V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:56:19

Freq. Stability -20C 3.3V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:56:32

Freq. Stability -10C 3.3V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:56:45

Freq. Stability 0C 3.3V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:56:58

Freq. Stability 10C 3.3V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:57:11

Freq. Stability 30C 3.3V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:57:37

Freq. Stability 40C 3.3V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:57:50

Freq. Stability 50C 3.3V n40 5670MHz Ant1 0 Minutes




Date: 20.09.2023 02:58:04

Freq. Stability 20C 2.81V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:01:56

Freq. Stability 20C 3.3V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:03:29

Freq. Stability 20C 3.80V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:02:23

Freq. Stability -20C 3.3V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:02:36

Freq. Stability -10C 3.3V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:02:49

Freq. Stability 0C 3.3V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:03:02

Freq. Stability 10C 3.3V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:03:15

Freq. Stability 30C 3.3V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:03:42

Freq. Stability 40C 3.3V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:03:55

Freq. Stability 50C 3.3V n40 5755MHz Ant1 0 Minutes




Date: 20.09.2023 05:04:08

Freq. Stability 20C 2.81V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:12:28

Freq. Stability 20C 3.3V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:14:00

Freq. Stability 20C 3.80V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:12:54

Freq. Stability -20C 3.3V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:13:08

Freq. Stability -10C 3.3V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:13:21

Freq. Stability 0C 3.3V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:13:34

Freq. Stability 10C 3.3V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:13:47

Freq. Stability 30C 3.3V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:14:14

Freq. Stability 40C 3.3V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:14:27

Freq. Stability 50C 3.3V n40 5795MHz Ant1 0 Minutes




Date: 20.09.2023 05:14:40

Freq. Stability 20C 2.81V n40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 22:51:34

Freq. Stability 20C 3.3V n40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 22:52:51

Freq. Stability 20C 3.80V n40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 22:51:56

Freq. Stability -20C 3.3V n40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 22:52:07

Freq. Stability -10C 3.3V n40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 22:52:18

Freq. Stability 0C 3.3V n40 5190MHz Ant2 0 Minutes




Date: 22.9.2023 22:52:29

Freq. Stability 10C 3.3V n40 5190MHz Ant2 0 Minutes




Date: 22.09.2023 22:52:40

Freq. Stability 30C 3.3V n40 5190MHz Ant2 0 Minutes




Date: 22.09.2023 22:53:02

Freq. Stability 40C 3.3V n40 5190MHz Ant2 0 Minutes




Date: 22.09.2023 22:53:13

Freq. Stability 50C 3.3V n40 5190MHz Ant2 0 Minutes




Date: 22.09.2023 22:53:24


Freq. Stability 20C 2.81V n40 5230MHz Ant2 0 Minutes



Freq. Stability 20C 3.3V n40 5230MHz Ant2 0 Minutes




Freq. Stability 20C 3.80V n40 5230MHz Ant2 0 Minutes




Date: 22.9.2023 22:57:33

Freq. Stability -20C 3.3V n40 5230MHz Ant2 0 Minutes




Date: 22.9.2023 22:58:04

Freq. Stability -10C 3.3V n40 5230MHz Ant2 0 Minutes




Date: 22.9.2023 22:58:15

Freq. Stability 0C 3.3V n40 5230MHz Ant2 0 Minutes




Date: 22.9.2023 22:58:26

Freq. Stability 10C 3.3V n40 5230MHz Ant2 0 Minutes




Date: 22.9.2023 22:58:37

Freq. Stability 30C 3.3V n40 5230MHz Ant2 0 Minutes




Date: 22.9.2023 22:58:59

Freq. Stability 40C 3.3V n40 5230MHz Ant2 0 Minutes




Date: 22.09.2023 22:59:10

Freq. Stability 50C 3.3V n40 5230MHz Ant2 0 Minutes




Date: 22.09.2023 22:59:21

Freq. Stability 20C 2.81V n40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:02:02

Freq. Stability 20C 3.3V n40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:03:20

Freq. Stability 20C 3.80V n40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 25:02:25

Freq. Stability -20C 3.3V n40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 25:02:36

Freq. Stability -10C 3.3V n40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:02:47

Freq. Stability 0C 3.3V n40 5270MHz Ant2 0 Minutes




Date: 22.9.2023 23:02:58

Freq. Stability 10C 3.3V n40 5270MHz Ant2 0 Minutes



Date: 22.9.2023 25:03:09

Freq. Stability 30C 3.3V n40 5270MHz Ant2 0 Minutes



Date: 22.9.2023 25:03:31


Freq. Stability 40C 3.3V n40 5270MHz Ant2 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.90 dB RBW 10 kHz
Att 30 dB SWT 80 ms VBW 30 kHz Mode Sweep

SGL Count 20/20

1Pk Max



Marker

Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1	1		5.27008 GHz	-32.93 dBm		
M2	1		5.25192 GHz	-20.61 dBm		
M3	1		5.28824 GHz	-19.96 dBm		

Date: 22.S7P.2023 25:03:42


Freq. Stability 50C 3.3V n40 5270MHz Ant2 0 Minutes

Spectrum

Ref Level 20.00 dBm Offset 3.90 dB RBW 10 kHz
Att 30 dB SWT 80 ms VBW 30 kHz Mode Sweep

SGL Count 20/20

1Pk Max




Marker

Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1	1		5.27 GHz	-30.35 dBm		
M2	1		5.25176 GHz	-21.43 dBm		
M3	1		5.28824 GHz	-21.45 dBm		


Date: 22.S7P.2023 25:03:53

Freq. Stability 20C 2.81V n40 5310MHz Ant2 0 Minutes




Date: 22.9.2023 23:06:33

Freq. Stability 20C 3.3V n40 5310MHz Ant2 0 Minutes




Date: 22.9.2023 23:08:10

Freq. Stability 20C 3.80V n40 5310MHz Ant2 0 Minutes




Date: 22.9.2023 23:07:15

Freq. Stability -20C 3.3V n40 5310MHz Ant2 0 Minutes




Date: 22.9.2023 23:07:26

Freq. Stability -10C 3.3V n40 5310MHz Ant2 0 Minutes




Date: 22.9.2023 23:07:37

Freq. Stability 0C 3.3V n40 5310MHz Ant2 0 Minutes




Date: 22.9.2023 23:07:48

Freq. Stability 10C 3.3V n40 5310MHz Ant2 0 Minutes




Date: 22.09.2023 23:07:59

Freq. Stability 30C 3.3V n40 5310MHz Ant2 0 Minutes




Date: 22.09.2023 23:08:21

Freq. Stability 40C 3.3V n40 5310MHz Ant2 0 Minutes




Date: 22.09.2023 23:08:32

Freq. Stability 50C 3.3V n40 5310MHz Ant2 0 Minutes




Date: 22.09.2023 23:08:43

Freq. Stability 20C 2.81V n40 5510MHz Ant2 0 Minutes




Date: 22.09.2023 23:15:29

Freq. Stability 20C 3.3V n40 5510MHz Ant2 0 Minutes




Date: 22.09.2023 23:17:01

Freq. Stability 20C 3.80V n40 5510MHz Ant2 0 Minutes




Date: 22.9.2023 23:15:36

Freq. Stability -20C 3.3V n40 5510MHz Ant2 0 Minutes




Date: 22.9.2023 23:16:09

Freq. Stability -10C 3.3V n40 5510MHz Ant2 0 Minutes




Date: 22.9.2023 25:16:22

Freq. Stability 0C 3.3V n40 5510MHz Ant2 0 Minutes




Date: 22.9.2023 25:16:35

Freq. Stability 10C 3.3V n40 5510MHz Ant2 0 Minutes




Date: 22.09.2023 23:16:48

Freq. Stability 30C 3.3V n40 5510MHz Ant2 0 Minutes




Date: 22.09.2023 23:17:14

Freq. Stability 40C 3.3V n40 5510MHz Ant2 0 Minutes



Date: 22.09.2023 25:17:27

Freq. Stability 50C 3.3V n40 5510MHz Ant2 0 Minutes



Date: 22.09.2023 25:17:40